





report date: 2024-03-28

General information

Make	MAZDA
Model	6 D SPORT NAV
Colour	Blue
Year of manufacture	2015
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 2.200 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	116 g/km
CO2 label	С



CarCheck.co.uk page 1/11



LG65SFJ

report date: 2024-03-28


Internet history

Entry 2

Date 2021-10-06

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-10-05	
Distruss	7	

Pictures 7

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-10-28
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	8
Total items failed	2

MOT #8	2023-10-20 10:39
MOT test number	661648334742
Result	√ Passed
Next expiry date	2024-10-28

MOT #7	2022-10-26 11:49
MOT test number	335316128343
Result	✓ Passed

MOT #6	2021-10-16 09:58
MOT test number	642791475823
Result	✓ Passed

MOT #5		2021-10-16 09:58
MOT test number		999280156724
Result		X Failed
Pass with rectification	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #4	2020-10-27 11:45
MOT test number	718709009849
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #3 2019-10-29 13:11

MOT test number 474341910638

Result ✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Windscreen damaged but not adversely affecting driver's view Zone b (3.2 (a) (i))

MOT #2 2019-10-24 10:05

MOT test number 196442534619

Result X Failed

Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view Zone b (3.2 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1 2018-10-22 14:14

MOT test number 238756739730

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	28 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Tyne	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	
manus .	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	NIP. IIK
Plate since	
Current registration	NK SIK
Plate since	
	More info >
	More into >

CarCheck.co.uk page 8/11



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-10-28
Last registration	2023-10-20
Complete history	See info



Registration #1	2015-10-28	13 mi
Registration #2	2018-10-22	93.265 mi
Registration #3	2019-10-24	102.139 mi
Registration #4	2019-10-29	102.204 mi
Registration #5	2020-10-27	110.342 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		10.777 es

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	****
Adult	92%
Children	77%
Pedestrian	66%
Safety systems	81%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1450 mm
Length	4870 mm
Wheel base	2750 mm
Kerb weight	1420 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	SH 30554522

CarCheck.co.uk page 11/11