





report date: 2024-03-28

### General information

Make	ABARTH
Model	PUNTO ABARTH SUPERSPORT
Colour	White
Year of manufacture	2014
Top speed	132 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	180 BHP
Max. torque	270 Nm at 2.500 rpm
Engine capacity	1.368 сс
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	142 g/km
CO2 label	F



CarCheck.co.uk page 1/13



# Internet history

### Entry 1

Date 2021-07-22

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-07-18
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	21
Total items failed	10

MOT #11		2023-07-19 09:11
MOT test	number	460607989995
Result		✓ Passed
Next expi	ry date	2024-07-18
Advice	Nearside Front Suspension arm corroded but not seriously weakened (5	5.3.3 (b) (i))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Rear Coil spring mounting corroded but not seriously weakened	d axle area (5.3.1 (b) (i))
Advice	Offside Front Suspension arm corroded but not seriously weakened (5.3	3.3 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice (b) (i))	Nearside Rear Lower Coil spring mounting corroded but not seriously w	veakened axle area (5.3.1

CarCheck.co.uk page 3/13



**KP14RTX** 

report date: 2024-03-28

**MOT #10** 2023-07-05 14:06

MOT test number 185950156213

Result X Failed

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Lower Coil spring mounting corroded but not seriously weakened axle area (5.3.1 (b) (i))

Advice Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Fail Nearside Rear Position lamp light intensity significantly reduced (4.2.3 (a) (ii))

**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear Coil spring mounting corroded but not seriously weakened axle area (5.3.1 (b) (i))

Advice Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #9 2022-07-06 11:16

MOT test number 514203333501

**Result** 
✓ Passed

MOT #8 2021-05-13 09:13

**MOT test number** 301854245251

Result \( \sqrt{Passed} \)

CarCheck.co.uk page 4/13



KP14RTX

report date: 2024-03-28

MOT test number

Result

Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice

Nearside Front Tyre slightly damaged/cracking or perishing Outer wall damaged (5.2.3 (d) (ii))

Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))

2020-05-19 09:27 **MOT #6 MOT** test number 748698795713 Result × Failed Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i)) **Advice** Nearside Front Tyre slightly damaged/cracking or perishing Outer wall damaged (5.2.3 (d) (ii)) Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i)) Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #5

MOT test number

149397704194

Result

✓ Passed

MOT #4

MOT test number

467431675896

Result

Pass with rectification
(ii))

Pass with rectification
Offside Headlamp aim too high (4.1.2 (a))

Pass with rectification
Nearside Headlamp aim too high (4.1.2 (a))

CarCheck.co.uk page 5/13



**KP14RTX** 

report date: 2024-03-28

MOT #3	2018-05-18 10:24
MOT test number	245809109433
Result	✓ Passed
MOT #2	2017-05-30 10:48
MOT test number	684394316103
Result	✓ Passed
MOT #1	2017-05-30 08:20
MOT test number	742864068632
Result	<b>×</b> Failed
Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	

CarCheck.co.uk page 6/13



# Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	18 July 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Venicle class	40
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this ABARTH. See if, where and when this ABARTH had damage and the car repair costs. We also check if this ABARTH was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra ABARTH salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this ABARTH in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Toport data: 2021 03 20

Owner history	
For how long did the current and previous owner(s) have this ABARTH? How many owner have? Check it in the premium report and see all owner registrations. Download the full it	
***************************************	
***************************************	
*********	
***************************************	
	More info >
Plate changes	
See in this check if this ABARTH had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this ABARTH is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this ABARTH has been settled.

If not, and you buy this ABARTH then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this ABARTH is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 11/13



# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-06-02
Last registration	2023-07-19
Complete history	See info



Registration #1	2014-06-02	8 mi
Registration #2	2017-05-30	9.682 mi
Registration #3	2017-05-30	9.683 mi
Registration #4	2018-05-18	15.057 mi
Registration #5	2019-05-15	20.875 mi
Registration #6	2019-05-15	20.875 mi
Registration #7	2020-05-19	23.737 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 ms
Registration #12		11.777 es
Registration #13		0.77 66

More info >

CarCheck.co.uk page 12/13



Llimanciane	J. WOIGH	-
Dimensions	a welali	ц.

Width	1726 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1185 kg
Max. allowed weight	1665 kg

# Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	1862496

CarCheck.co.uk page 13/13