




report date: 2024-03-28

General information

Make	CITROEN
Model	GRAND C4 PICASSO 16V VTR PLUS GRAND PICASSO
Colour	Purple
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	10.1 mpg
Consumption extra urban	6.0 mpg
Consumption combined	7.5 mpg
CO2 emission	177 g/km
CO2 label	I



**MOT history**

MOT expiry date	2021-09-13
MOT pass rate	53 %
MOT passed	10
Failed MOT tests	9
Total advice items	38
Total items failed	29

MOT #19 2020-09-14 12:11**MOT test number** 734967965107**Result** ✓ Passed**Next expiry date** 2021-09-13**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Tyre worn close to legal limit/worn on edge Worn significantly on inner & outer edges (5.2.3 (e))**MOT #18** 2020-09-12 15:13**MOT test number** 423397122962**Result** ✗ Failed**Advice** Rear Brake drum worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**Advice** Front Tyre worn close to legal limit/worn on edge Worn significantly on inner & outer edges (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #17** 2020-02-11 08:06**MOT test number** 752922119071**Result** ✓ Passed

**MOT #16** 2020-02-10 16:54**MOT test number** 950953421105**Result** ✗ Failed

- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #15 2018-11-30 11:29**MOT test number** 227009379849**Result** ✓ Passed**MOT #14** 2017-12-08 11:25**MOT test number** 779585110094**Result** ✓ Passed

- Advice** Oil leak

MOT #13 2017-12-01 12:23**MOT test number** 185812044900**Result** ✗ Failed

- Fail** Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front Wheel bolt(s) missing (4.2.A.1e)
- Advice** Oil leak

MOT #12 2016-12-05 11:18**MOT test number** 527490864885**Result** ✓ Passed



MOT #11

2016-12-01 12:23

MOT test number

632876107075

Result

✗ Failed

Fail

Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

Advice

Fuel tank covers broken

Fail

Offside Front position lamp(s) not working (1.1.A.3b)

Fail

Electronic stability system warning lamp indicates a fault (3.4.1c)

Advice

Boot switch loose and may fail to open soon

Advice

Wrong size tyres fitted to all wheels

Fail

Nearside Front position lamp(s) not working (1.1.A.3b)

Advice

Nearside Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #10**

2016-11-21 15:40

MOT test number

957017711691

Result

✗ Failed

- Advice** Nearside Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Wrong size tyres fitted to all wheels
- Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Advice** Boot switch loose and may fail to open soon
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** EMI light on
- Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)
- Fail** Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Advice** Fuel tank covers broken

MOT #9

2015-12-05 11:02

MOT test number

840117188875

Result

✓ Passed

MOT #8

2014-11-27 09:43

MOT test number

599531134323

Result

✓ Passed

- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Notice** Nail in nearside rear tyre
- Notice** Vehicle's internal headlight adjuster altered to recheck lights

**MOT #7**

2014-11-27 09:43

MOT test number

247891534335

Result**✗ Failed****Notice** Nail in nearside rear tyre**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #6**

2013-11-19 17:35

MOT test number

637583423379

Result**✓ Passed****Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** N/s rear tyre cracking**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #5**

2013-11-19 14:53

MOT test number

845033523397

Result**✗ Failed****Fail**

Emissions not tested (7.0)

Advice

Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Fail

Offside Headlamp aim too high (1.8)

Fail

Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice

Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail

Nearside Stop lamp not working (1.2.1b)

Fail

Front Brakes imbalanced across an axle (3.7.B.5b)

Notice

N/s rear tyre cracking

MOT #4

2012-11-30 09:54

MOT test number

967255832339

Result**✓ Passed****Notice**

Nail in nearside rear tyre

Advice

Tyre worn close to the legal limit (4.1.E.1)

Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**MOT #3** 2012-11-30 09:54**MOT test number** 435375832310**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside rear tyre**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #2** 2011-12-07 14:46**MOT test number** 699531741348**Result** ✓ Passed**MOT #1** 2011-12-01 15:35**MOT test number** 597635831357**Result** ✗ Failed**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)



Tax & MOT check

✕
Untaxed

Tax expired:
31 January 2021

✕
MOT

Expired:
13 September 2021

Tax status	Expired at 31 January 2021
Days left	1183 days too late
MOT expiry date	13 September 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 FP58VHF
Plate since	2019-09-28
Current registration	 FP58VHF
Plate since	2019-09-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-01-09
Last registration	2020-09-14
Complete history	See info



Registration #1	2009-01-09	11 mi
Registration #2	2011-12-01	14.842 mi
Registration #3	2011-12-07	14.850 mi
Registration #4	2012-11-30	26.242 mi
Registration #5	2013-11-19	38.044 mi
Registration #6	2013-11-19	38.044 mi
Registration #7	2014-11-27	50.319 mi
Registration #8	2015-12-05	60.878 mi
Registration #9	2016-11-21	69.672 mi
Registration #10	2016-11-21	69.672 mi
Registration #11	2016-11-21	69.672 mi
Registration #12	2016-11-21	69.672 mi
Registration #13	2016-11-21	69.672 mi
Registration #14	2016-11-21	69.672 mi
Registration #15	2016-11-21	69.672 mi
Registration #16	2016-11-21	69.672 mi
Registration #17	2016-11-21	69.672 mi
Registration #18	2016-11-21	69.672 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1831 mm
Height	1665 mm
Length	4468 mm
Wheel base	2728 mm
Kerb weight	1458 kg
Max. allowed weight	2200 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	FHAZ0427944