



report date: 2024-03-28

General information

Make	MAZDA
Model	6 D SPORT
Colour	Grey
Year of manufacture	2010
Top speed	135 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 1.800 rpm
Engine capacity	2.183 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	142 g/km
CO2 label	F






Internet history

Entry 2

Date	2021-09-17
Pictures	14
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-10-03
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	25
Total items failed	7

MOT #14	2023-10-02 06:49
MOT test number	893178499220
Result	✓ Passed
Next expiry date	2024-10-03
Advice	Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))

MOT #13	2022-09-29 14:23
MOT test number	515258175104
Result	✓ Passed
Advice	Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
Advice	Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))

MOT #12	2021-09-28 12:43
MOT test number	878331375395
Result	✓ Passed

**MOT #11**

2020-09-30 15:10

**MOT test number**

931020532575

**Result**

✓ Passed

**Advice**

Under trays ftd

**Advice**

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice**

All underside showing corrosion

**Advice**

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10**

2019-09-30 16:13

**MOT test number**

247256798433

**Result**

✓ Passed

**Minor**

Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #9**

2019-09-30 15:26

**MOT test number**

138668127718

**Result**

✗ Failed

**Fail**

Offside Front Position lamp not working (4.2.1 (a) (ii))

**Fail**

Offside Front Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Minor**

Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Fail**

Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #8**

2018-10-01 09:49

**MOT test number**

984409238265

**Result**

✓ Passed

**Advice**

Rear suspension shows light corrosion

**Minor**

Offside Front Upper Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #7**

2017-10-04 14:11

**MOT test number**

611216493399

**Result**

✓ Passed

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Play in steering rack inner joint(s)**Advice** Dpf warning light on at test**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Nearside Front tyre worn to inner and outer edges**MOT #6**

2017-10-02 13:09

**MOT test number**

415080042338

**Result**

✗ Failed

**Advice** Offside Front Play in steering rack inner joint(s)**Fail** Driver's seat insecure (6.2.A.1)**Advice** Dpf warning light on at test**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Front wheel bearing has excessive play (2.5.A.3c)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Front position lamp(s) not working os and ns (1.1.A.3b)**Advice** Nearside Front tyre worn to inner and outer edges**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



<b>MOT #5</b>	2016-10-03 16:17
<b>MOT test number</b>	800084582229
<b>Result</b>	✓ Passed
<b>Advice</b> Nearside Rear Brake pad(s) wearing thin (3.5.1g)	

<b>MOT #4</b>	2015-09-15 12:05
<b>MOT test number</b>	747296668926
<b>Result</b>	✓ Passed

<b>MOT #3</b>	2014-09-22 09:53
<b>MOT test number</b>	247935364278
<b>Result</b>	✓ Passed
<b>Notice</b> Under-trays fitted obscuring some underside components	

<b>MOT #2</b>	2013-08-28 14:28
<b>MOT test number</b>	776890643200
<b>Result</b>	✓ Passed

<b>MOT #1</b>	2013-08-28 12:30
<b>MOT test number</b>	829540743277
<b>Result</b>	✗ Failed
<b>Fail</b> Front registration plate deteriorated (6.3.1d)	



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 July 2024

✓  
**MOT**  
  
Expires:  
3 October 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	3 October 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-




Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-23
Last registration	2023-10-02
Complete history	<a href="#">See info</a>



Registration #1	2010-09-23	27 mi
Registration #2	2013-08-28	58.116 mi
Registration #3	2013-08-28	58.116 mi
Registration #4	2014-09-22	66.716 mi
Registration #5	2015-09-15	75.466 mi
Registration #6	2016-10-03	86.988 mi
Registration #7	2017-10-02	96.308 mi
Registration #8	2017-10-04	96.338 mi
Registration #9	2018-09-20	96.338 mi
Registration #10	2019-09-20	96.338 mi
Registration #11	2020-09-20	96.338 mi
Registration #12	2021-09-20	96.338 mi
Registration #13	2022-09-20	96.338 mi
Registration #14	2023-09-20	96.338 mi
Registration #15	2023-09-20	96.338 mi
Registration #16	2023-10-02	96.338 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Kerb weight	1555 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R2 10241636