



report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 BLUEHDI DSIRE
Colour	Red
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	80.7 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-01-29
Pictures	7
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2025-04-28
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	16
Total items failed	3

MOT #10	2024-04-24 13:32
MOT test number	735823314770
Result	✓ Passed
Next expiry date	2025-04-28

MOT #9	2023-04-27 09:50
MOT test number	727625101900
Result	✓ Passed

MOT #8	2022-04-04 12:54
MOT test number	657562043419
Result	✓ Passed
Advice	Coolant leak

MOT #7	2021-04-29 15:06
MOT test number	735807173742
Result	✓ Passed

MOT #6	2020-08-07 10:55
MOT test number	961315151011
Result	✓ Passed

**MOT #5** 2020-08-07 10:23**MOT test number** 279670778737**Result** ✗ Failed**Fail** Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2019-08-08 15:43**MOT test number** 203306510255**Result** ✓ Passed**MOT #3** 2018-10-12 13:55**MOT test number** 616016217794**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing 205/45/17 (5.2.3 (d) (ii))

**MOT #2** 2018-10-12 11:29**MOT test number** 474535475974**Result** ✗ Failed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing 205/45/17 (5.2.3 (d) (ii))**Fail** Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #1** 2017-10-05 12:33**MOT test number** 970610013494**Result** ✓ Passed**Advice** Offside front tyre wearing on the inside edge**Advice** Offside front wheel has slight damage to the inner bead rim**Advice** Nearside front tyre wearing on the inside edge , also has slight damage on the outer wall



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
28 April 2025

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	366
<b>MOT expiry date</b>	28 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>PX64XUK</b>
Plate since	2024-03-29
Current registration	<b>PX64XUK</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-30
Last registration	2024-04-24
Complete history	<a href="#">See info</a>



Registration #1	2014-09-30	29 mi
Registration #2	2017-10-05	21.531 mi
Registration #3	2018-10-12	29.526 mi
Registration #4	2018-10-12	29.526 mi
Registration #5	2019-08-08	32.827 mi
Registration #6	2020-08-07	39.556 mi
Registration #7	2020-08-07	39.556 mi
Registration #8	2020-08-07	39.556 mi
Registration #9	2020-08-07	39.556 mi
Registration #10	2020-08-07	39.556 mi
Registration #11	2020-08-07	39.556 mi
Registration #12	2020-08-07	39.556 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1090 kg
Max. allowed weight	1598 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBGX3002976