





report date: 2024-03-28

General information

Make	PEUGEOT
Model	208 BLUE HDI S/S SW ACTIVE
Colour	Black
Year of manufacture	2016
Top speed	114 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	88.3 mpg
Consumption combined	80.7 mpg
CO2 emission	94 g/km
CO2 label	A



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1


Date 2021-02-04

Pictures 4

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2025-04-24
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	26
Total items failed	6

MOT #9		2024-04-25 09:52
MOT test	number	457728318368
Result		✓ Passed
Next exp	iry date	2025-04-24
Minor (i))	Offside Registration plate lamp inoperative in the case of multiple lamps or l	ight sources (4.7.1 (b)
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))	

MOT #8	2024-04-24 14:54
MOT test number	463854360421
Result	× Failed
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or (i))	light sources (4.7.1 (b)
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice Rear Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #7 2023-04-06 14:59 **MOT** test number 898156647240 Result ✓ Passed **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Rear exhaust hanger broken. Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #6 2023-04-06 11:15 **MOT** test number 677887880276 Result × Failed **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) Fail Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Oil leak, but not excessive (8.4.1 (a) (i)) **Advice** Rear exhaust hanger broken. Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

Result

Advice
Oil leak, but not excessive (8.4.1 (a) (i))

Advice
Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice
Rear Exhaust mounting defective (6.1.2 (a))

MOT #4 2021-01-25 16:11

MOT test number 738100308161

Result ✓ Passed

MOT #3 2021-01-19 19:40 457722136715 **MOT** test number Result × Failed Fail Nearside Front Headlamp not working on dipped beam 205/45/17 (4.1.1 (a) (ii)) **Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

796522692084

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Nearside outer driveshaft gaiter leaking grease

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #1 2019-09-17 13:37

MOT test number 507634063811

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	24 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

SD660NK

report date: 2024-03-28

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		GEOT
HEREER PARTY AND ADDRESS OF THE PARTY AND ADDR		

HARMAN AND AND AND AND AND AND AND AND AND A		

	More info	>

Plate changes

See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	
Plate since	m.o.o
Current registration	SIE UK
Plate since	

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-10-13
Last registration	2024-04-25
Complete history	See info



Registration #1	2016-10-13	22 mi
Registration #2	2019-09-17	40.790 mi
Registration #3	2020-09-18	51.093 mi
Registration #4	2021-01-19	52.981 mi
Registration #5	2021-01-25	52.981 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		77.777 mg

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditionin
S0295	
50482	
50501	
60566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	92%
Children	79%
Pedestrian	64%
Safety systems	81%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1563 mm
Height	1472 mm
Length	4585 mm
Wheel base	2730 mm
Kerb weight	1200 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	53 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/1

Number of axles 2

Engine number JBGZ3062220