



report date: 2024-03-28

General information

Make	KIA
Model	PICANTO 1
Colour	Blue
Year of manufacture	2017
Top speed	100 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	66 BHP
Max. torque	96 Nm at 3.500 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	76.4 mpg
Consumption combined	64.2 mpg
CO2 emission	101 g/km
CO2 label	B





## Internet history

### Entry 3



Date	2021-06-08
Pictures	23
Listing price	<a href="#">View report</a>



source: yesauto.com

### Entry 2



Date	2021-05-21
Pictures	24
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

### Entry 1

Date	2021-05-21
Pictures	24
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-09-17
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	6
Total items failed	2

MOT #7	2023-09-18 10:05
MOT test number	631941391975
Result	✓ Passed
Next expiry date	2024-09-17

MOT #6	2023-03-15 09:31
MOT test number	800653331315
Result	✓ Passed
Advice	Front Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))
Advice	Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))

MOT #5	2022-03-28 08:18
MOT test number	788125670996
Result	✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #4** 2022-03-28 08:18**MOT test number** 625781353291**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2021-04-01 14:20**MOT test number** 682234822621**Result** ✓ Passed**MOT #2** 2021-03-25 16:10**MOT test number** 807497746459**Result** ✗ Failed**Fail** Offside Side repeater not working (4.4.1 (a) (ii))**MOT #1** 2020-09-03 15:40**MOT test number** 497352118031**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 March 2025

✓  
**MOT**

**Expires:**  
17 September 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	17 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>First licence fee (12 months)</b>	£ 185,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>NJ67MKM</b>
Plate since	2019-09-29
Current registration	<b>NJ67MKM</b>
Plate since	2019-09-29

More info >





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-09-07
Last registration	2023-09-18
Complete history	<a href="#">See info</a>



Registration #1	2017-09-07	16 mi
Registration #2	2020-09-03	9.616 mi
Registration #3	2021-03-25	10.905 mi
Registration #4	2021-04-01	10.905 mi
Registration #5	2022-09-18	10.905 mi
Registration #6	2023-09-18	10.905 mi
Registration #7	2023-09-18	10.905 mi
Registration #8	2023-09-18	10.905 mi
Registration #9	2023-09-18	10.905 mi
Registration #10	2023-09-18	10.905 mi
Registration #11	2023-09-18	10.905 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	83%
Pedestrian	47%
Safety systems	43%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1595 mm
Height	1485 mm
Length	3595 mm
Kerb weight	1028 kg
Max. allowed weight	1400 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

**Engine number**

G3LAHD045769