



General information

Make	FORD
Model	MONDEO TITANIUM X TDCI 140
Colour	Silver
Year of manufacture	2009
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G








Internet history

Entry 1

Date	2021-07-16
Pictures	40
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-04-10
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	68
Total items failed	14

MOT #19	2023-04-11 16:14
---------	------------------

MOT test number	923619695907
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-04-10
------------------	------------

- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside sun visor slightly loose
- Advice** General under body corrosion
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Exhaust heat shield slightly loose

**MOT #18**

2023-04-11 11:14

**MOT test number**

197958250916

**Result****✗ Failed****Fail** Exhaust emissions exceed manufacturer's specified limit Plate value 0.50 (8.2.2.2 (a))**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Advice** Exhaust heat shield slightly loose**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Brake pedal wearing smooth (1.1.2 (c))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** General under body corrosion**Advice** Offside sun visor slightly loose**MOT #17**

2022-01-29 16:37

**MOT test number**

964806853186

**Result****✓ Passed****Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Sun visor slightly loose**Advice** Exhaust heat shield coming loose.**Advice** Brake pedal wearing smooth (1.1.2 (c))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Advice** General underbody surface corrosion .**Advice** Front Tyre worn close to legal limit/worn on edge Both worn at edges. (5.2.3 (e))

**MOT #16**

2022-01-29 10:20

**MOT test number**

558929361974

**Result****✗ Failed****Advice**

General underbody surface corrosion .

**Advice**

Brake pedal wearing smooth (1.1.2 (c))

**Fail**

Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Fail**

Brake performance not tested (1.2.1 (g))

**Advice**

Offside Sun visor slightly loose

**Advice**

Exhaust heat shield coming loose.

**Fail**

Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**Advice**

Front Tyre worn close to legal limit/worn on edge Both worn at edges. (5.2.3 (e))

**Advice**

Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**Advice**

Rear Exhaust mounting defective (6.1.2 (a))

**Minor**

Nearside Rear Tyre obviously under inflated (5.2.3 (l))

**MOT #15**

2021-12-01 15:26

**MOT test number**

742326275848

**Result****✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing on both edges (5.2.3 (e))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Exhaust system and brackets corroding
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing on both edges (5.2.3 (e))
- Advice** Play in steering rack inner joint(s) nearside and offside front
- Advice** Various front and rear steering, braking and suspension components are corroding
- Fail** Engine MIL inoperative or indicates a malfunction engine covers and Undertrays fitted (8.2.1.2 (h))
- Advice** Diesel fumes smell coming from vehicle no obvious signs of any fuel leaks

**MOT #14**

2020-12-18 15:24

**MOT test number**

121723497202

**Result****✓ Passed****MOT #13**

2020-12-18 15:24

**MOT test number**

857957402337

**Result****✗ Failed**

- Pass with rectification** Offside Parking brake inoperative on one side (1.4.1 (a))
- Pass with rectification** Offside Rear Brake cable damaged parking brake (1.1.15 (a))
- Pass with rectification** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

**MOT #12** 2019-12-03 12:03**MOT test number** 443011307986**Result** ✓ Passed

- Advice** 1 x rear exhaust mount broken
- Advice** Nearside Front Tyre slightly damaged outer sidewall (5.2.3 (d) (ii))
- Advice** Engine cover & under tray fitted obscuring view of some testable items

**MOT #11** 2019-11-30 11:47**MOT test number** 284411417624**Result** ✗ Failed

- Fail** Nearside Rear Suspension arm pin or bush excessively worn front positioned bush (5.3.4 (a) (i))
- Advice** 1 x rear exhaust mount broken
- Advice** Engine cover & under tray fitted obscuring view of some testable items
- Fail** Offside Rear Suspension arm pin or bush excessively worn front positioned bush (5.3.4 (a) (i))
- Advice** Nearside Front Tyre slightly damaged outer sidewall (5.2.3 (d) (ii))

**MOT #10** 2018-12-05 15:09**MOT test number** 583297572170**Result** ✓ Passed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Front Items removed from driver's view prior to test

**MOT #9** 2018-12-05 10:32**MOT test number** 296594794942**Result** ✗ Failed

- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Front Items removed from driver's view prior to test

**MOT #8** 2017-11-28 10:59**MOT test number** 596130288787**Result** ✓ Passed

- Advice** Play in steering rack inner joint(s)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #7** 2016-12-06 16:51**MOT test number** 926135735634**Result** ✓ Passed**MOT #6** 2016-12-06 11:39**MOT test number** 828004289254**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Registration plate lamp not working (1.1.C.1d)



**MOT #5** 2016-08-09 09:29**MOT test number** 361955898862**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2015-05-12 12:20**MOT test number** 449092035170**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2014-05-08 11:47**MOT test number** 215838824454**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Items removed from driver's view prior to test**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-05-15 15:00**MOT test number** 988165733116**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Items removed from driver's view prior to test**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2012-05-23 09:42
MOT test number	508074342168
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 August 2024

✗  
**MOT**  
  
Expired:  
10 April 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	10 April 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-10-14
Last registration	2023-04-11
Complete history	<a href="#">See info</a>



Registration #1	2009-10-14	9 mi
Registration #2	2012-05-23	42.343 mi
Registration #3	2013-05-15	49.878 mi
Registration #4	2014-05-08	56.544 mi
Registration #5	2015-05-12	60.660 mi
Registration #6	2016-08-09	65.139 mi
Registration #7	2016-12-06	66.269 mi
Registration #8	2016-12-06	66.270 mi
Registration #9	2017-11-28	76.840 mi
Registration #10	2018-12-05	88.409 mi
Registration #11	2018-12-05	88.410 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi
Registration #18	2019-05-29	95.377 mi
Registration #19	2019-05-29	95.377 mi
Registration #20	2019-05-29	95.377 mi
Registration #21	2019-05-29	95.377 mi

More info >





Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

**Engine number**

9B03425