



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Yellow
Year of manufacture	2008
Top speed	111 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.595 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	46.3 mpg
Consumption combined	36.2 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-10-18
Pictures	44
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-09-28
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	7
Total items failed	8

MOT #17	2023-09-26 12:16
MOT test number	181914539096
Result	✓ Passed
Next expiry date	2024-09-28
Advice	Exhaust emits blue smoke during acceleration (8.2.1.2 (g))

MOT #16	2022-09-19 06:07
MOT test number	543727406246
Result	✓ Passed

MOT #15	2022-09-15 19:55
MOT test number	947450420621
Result	✗ Failed
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Fail	Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Fail	Offside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))

**MOT #14** 2021-09-29 09:32**MOT test number** 195663322092**Result** ✓ Passed**MOT #13** 2021-01-15 12:47**MOT test number** 591984860976**Result** ✓ Passed**MOT #12** 2020-01-22 09:35**MOT test number** 134457471949**Result** ✓ Passed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge very close to cords being exposed (5.2.3 (e))

**MOT #11** 2020-01-22 09:34**MOT test number** 283548710073**Result** ✗ Failed

**Pass with rectification** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge very close to cords being exposed (5.2.3 (e))

**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #10** 2019-01-22 14:57**MOT test number** 739844274772**Result** ✓ Passed**MOT #9** 2019-01-22 10:00**MOT test number** 318276094862**Result** ✗ Failed

**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



<b>MOT #8</b>	2018-01-22 09:33
<b>MOT test number</b>	919163115073
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
<b>Advice</b>	Items removed from driver's view prior to test
<b>Advice</b>	Rear Brake pad(s) wearing thin (3.5.1g)
<b>MOT #7</b>	2017-01-21 09:49
<b>MOT test number</b>	616870599977
<b>Result</b>	✓ Passed
<b>MOT #6</b>	2016-01-16 10:35
<b>MOT test number</b>	886373342806
<b>Result</b>	✓ Passed
<b>MOT #5</b>	2015-01-21 09:37
<b>MOT test number</b>	139431725427
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2014-01-21 09:35
<b>MOT test number</b>	156581824062
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2013-01-21 10:28
<b>MOT test number</b>	316901723002
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2012-01-19 11:43
<b>MOT test number</b>	385759512029
<b>Result</b>	✓ Passed



MOT #1	2011-01-12 10:45
MOT test number	775912311024
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
28 September 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	154
<b>MOT expiry date</b>	28 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>YN57ZRT</b>
Plate since	2024-03-29
Current registration	 <b>YN57ZRT</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-01-24
Last registration	2023-09-26
Complete history	<a href="#">See info</a>



Registration #1	2008-01-24	23 mi
Registration #2	2011-01-12	9.911 mi
Registration #3	2012-01-19	14.392 mi
Registration #4	2013-01-21	19.048 mi
Registration #5	2014-01-21	21.223 mi
Registration #6	2015-01-21	23.640 mi
Registration #7	2016-01-16	32.895 mi
Registration #8	2017-01-21	57.561 mi
Registration #9	2018-01-22	72.189 mi
Registration #10	2019-01-22	90.948 mi
Registration #11	2020-01-22	90.948 mi
Registration #12	2021-01-22	90.948 mi
Registration #13	2022-01-22	90.948 mi
Registration #14	2023-01-22	90.948 mi
Registration #15	2024-01-22	90.948 mi
Registration #16	2025-01-22	90.948 mi
Registration #17	2026-01-22	90.948 mi
Registration #18	2027-01-22	90.948 mi
Registration #19	2028-01-22	90.948 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2516 mm
Kerb weight	1393 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	BFS070411