





report date: 2024-03-28

General information

Make	BMW
Model	530 530D SE
Colour	Black
Year of manufacture	2005
Top speed	151 mph
0 - 60 mph	7.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	215 BHP
Max. torque	500 Nm at 2.000 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	26.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	36.2 mpg
CO2 emission	208 g/km
CO2 label	K



CarCheck.co.uk page 1/14



MOT history

MOT expiry date	2023-02-01
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	68
Total items failed	11

MOT #20	2022-02-02 12:52
MOT test number	640711514854
Result	✓ Passed
Next expiry date	2023-02-01
Advice Nearside Front Lower Track rod end ball joint has slight play (2.1.3 (b) (i))	

MOT #19	2021-02-02 16:06
MOT test number	690283531313
Result	✓ Passed
Advice Nearside Front Lower Anti-roll bar linkage ball joint has slight play (5.3.4 ((a) (i))
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice Offside Rear handbrake only just meets standard	

CarCheck.co.uk page 2/14



Result

VK05SKE

✓ Passed

MOT #18 2020-01-22 09:47

MOT test number 925734701385

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Nearside Near Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Brake hose slightly deteriorated perished (1.1.12 (b) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

Advice Supplementary restraint system warning lamp does not illuminate (7.1.6 (a))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Brake hose slightly deteriorated perished (1.1.12 (b) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened lipped (1.1.14 (a) (ii))

MOT #17 2020-01-21 12:11

MOT test number 202116413660

Result X Failed

Fail Offside Front Position lamp with a multiple light source more than 1/2 not functioning 2x halos (4.2.1 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

Fail Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt upper cover (5.3.4 (b) (ii))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Brake hose slightly deteriorated perished (1.1.12 (b) (ii))

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened lipped (1.1.14 (a) (ii))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Brake hose slightly deteriorated perished (1.1.12 (b) (ii))

CarCheck.co.uk page 3/14



✓ Passed

✓ Passed

MOT #16 2019-01-28 13:03

MOT test number 883182426893

Result ✓ Passed

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #15 2018-01-17 15:02

MOT test number 500794909072

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Rear Nail in tyre

Result

Result

Advice Supplementary Restraint System warning lamp does not illuminate (5.4.2)

MOT #14 2017-01-23 16:37

MOT test number 535356368277

Advice Engine covers fitted

Advice Nearside Front Brake hose slightly deteriorated (3.6.B.4d)

Advice Scratches on front screen

Advice Sill covers fitted

Advice Offside Front Brake hose slightly deteriorated (3.6.B.4d)

CarCheck.co.uk page 4/14



MOT #13 2017-01-23 12:03

MOT test number 667108701475

Result X Failed

Advice Scratches on front screen

Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)

Advice Sill covers fitted

Advice Nearside Front Brake hose slightly deteriorated (3.6.B.4d)

Advice Engine covers fitted

Fail Nearside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Offside Front Brake hose slightly deteriorated (3.6.B.4d)

MOT #12 2016-02-01 15:19

MOT test number 268152947466

Result ✓ Passed

Advice Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Slight oil leak

Advice Offside Rear Brake hose slightly deteriorated (3.6.B.4d)

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/14



VK05SKE

report date: 2024-03-28

MOT #11		2015-01-12 16:22
MOT test	number	215792215002
Result		✓ Passed
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Notice	Under-trays fitted obscuring some underside components	
Notice	Items removed from driver's view prior to test	
Advice	Supplementary Restraint System warning lamp does not illuminate (5.4.2)	
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Sill covers fitted	

MOT #10		2015-01-12 16:22
MOT test	number	556982415069
Result		X Failed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Sill covers fitted	
Pass wi	th rectification Offside Side repeater not working (1.4.A.2c)	
Advice	Supplementary Restraint System warning lamp does not illuminate (5.4.2)	
Notice	Under-trays fitted obscuring some underside components	
Notice	Items removed from driver's view prior to test	
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Notice	Child seat fitted not allowing full inspection of adult belt	

MOT #9	2014-02-01 11:30
MOT test number	119372434091
Result	✓ Passed

CarCheck.co.uk page 6/14



VK05SKE

report date: 2024-03-28

MOT #8	2013-01-22 11:46

MOT test number 626442623094

Result ✓ Passed

MOT #7 2012-01-26 16:04

MOT test number 379556022018

Result ✓ Passed

MOT #6 2011-02-01 17:16

MOT test number 555882431089

Result \(\sqrt{Passed} \)

MOT #5 <u>2010-02-01 14:08</u>

MOT test number 552392630016

Result ✓ Passed

MOT #4 2009-04-10 12:39

MOT test number 882190509123

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Child seat fitted not allowing full inspection of adult belt

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system

requires adjustment or repair. (3.7.B.7)


Notice Underside and engine covers fitted restricting full inspection of areas and components

CarCheck.co.uk page 7/14



VK05SKE

report date: 2024-03-28



MOT #2	2009-03-20 15:52
MOT test number	171239879476
Result	X Failed
Fail Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Notice Nail in rear tyre	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail Parking brake: efficiency below requirements (3.7.B.7)	
Notice Child seat fitted not allowing full inspection of adult belt	

MOT #1	2008-04-08 12:37
MOT test number	241979298067
Result	✓ Passed
Notice O/s/r tyre low tread Notice O/s/f shock absorber top mounting rubber slightly deteriorated	

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners di Check it in the premium report and see all owner registrations. Download the full report <u>has</u>	
manage of the same	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	UK Miss
Plate since	
Current registration	NK NA
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-04-18
Last registration	2022-02-02
Complete history	See info



Registration #1	2005-04-18	18 mi
Registration #2	2008-04-08	54.859 mi
Registration #3	2009-03-20	75.120 mi
Registration #4	2009-04-10	76.149 mi
Registration #5	2010-02-01	83.744 mi
Registration #6	2011-02-01	89.515 mi
Registration #7	2012-01-26	95.486 mi
Registration #8	2013-01-22	100.378 mi
Registration #9	2014-02-01	105.132 mi
Registration #10	2015-01-12	113.948 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.177 ms

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditionin
50295	
50482	
50501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1846 mm
Height	1468 mm
Length	4841 mm
Wheel base	2888 mm
Kerb weight	1670 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 14/14

Number of axles 2

Engine number 34235901