



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE R-DESIGN
Colour	Black
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-08
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #16</b>	2021-11-09 12:03
<b>MOT test number</b>	347481404258
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-11-08

<b>MOT #15</b>	2020-07-27 16:29
<b>MOT test number</b>	456349452961
<b>Result</b>	✓ Passed

**Advice** Offside Rear Bumper mountings corroded but not likely to become detached bracket (6.1.4 (a) (i))

<b>MOT #14</b>	2020-07-27 08:43
<b>MOT test number</b>	372430671397
<b>Result</b>	✗ Failed

**Fail** Oil leaking excessively from engine Bottom engine (8.4.1 (a) (i))

**Advice** Offside Rear Bumper mountings corroded but not likely to become detached bracket (6.1.4 (a) (i))

<b>MOT #13</b>	2019-07-01 15:46
<b>MOT test number</b>	995476650687
<b>Result</b>	✓ Passed

**Advice** Rear tyres wearing out of shape

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

**Minor** Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

**MOT #12**

2019-07-01 10:32

**MOT test number**

956828623245

**Result****✗ Failed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Minor** Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Rear tyres wearing out of shape**Fail** Offside Front Suspension arm pin or bush excessively worn rear wishbone bush (5.3.4 (a) (i))**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**MOT #11**

2018-07-03 14:23

**MOT test number**

163609936373

**Result****✓ Passed****MOT #10**

2018-07-03 09:07

**MOT test number**

751116276255

**Result****✗ Failed****Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #9**

2017-07-24 14:21

**MOT test number**

689109325285

**Result****✓ Passed**

**MOT #8** 2016-12-22 14:55**MOT test number** 938933941665**Result** ✓ Passed**MOT #7** 2016-12-22 14:55**MOT test number** 737159153050**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Pass with rectification** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #6** 2015-12-14 12:25**MOT test number** 584526047252**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-12-23 09:30**MOT test number** 206767654380**Result** ✓ Passed

**MOT #4** 2014-08-06 10:41**MOT test number** 855098014273**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Notice** Outer sill covers fitted only partial check
- Advice** Offside Rear reflector slightly damaged but function not impaired (1.5.1c)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Rear Seat belt damaged but not affecting the operation of the belt (5.2.2a)

**MOT #3** 2013-08-14 08:56**MOT test number** 518066923206**Result** ✓ Passed

- Notice** Nearside rear seat belt buckel case missing
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Front tyres wearing on inner edges
- Notice** Sill trims fitted, partial examination only
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Rear tyres begining to wear on inner edge



MOT #2	2013-08-14 08:56
MOT test number	777176023262
Result	✗ Failed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Sill trims fitted, partial examination only
Notice	Rear tyres beginning to wear on inner edge
Pass with rectification	Offside Headlamp aim too low (1.8)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Nearside rear seat belt buckel case missing
Notice	Front tyres wearing on inner edges

MOT #1	2013-01-24 14:46
MOT test number	797254923040
Result	✓ Passed
Notice	Both front and rear inner brake pads appear low



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-10-20
Last registration	2021-11-09
Complete history	<a href="#">See info</a>



Registration #1	2009-10-20	7 mi
Registration #2	2013-01-24	33.394 mi
Registration #3	2013-08-14	42.884 mi
Registration #4	2014-08-06	56.541 mi
Registration #5	2014-12-23	60.907 mi
Registration #6	2015-12-14	73.103 mi
Registration #7	2016-12-22	82.380 mi
Registration #8	2016-12-22	82.380 mi
Registration #9	2017-07-24	87.264 mi
Registration #10	2018-01-20	91.277 mi
Registration #11	2018-01-20	91.277 mi
Registration #12	2018-01-20	91.277 mi
Registration #13	2018-01-20	91.277 mi
Registration #14	2018-01-20	91.277 mi
Registration #15	2018-01-20	91.277 mi
Registration #16	2018-01-20	91.277 mi
Registration #17	2018-01-20	91.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1381 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	704037