





report date: 2024-03-29

General information

Make	LAND ROVER
Model	FREELANDER TD4 COMMERCIAL
Colour	Black
Year of manufacture	-
Gearbox	5 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	260 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/14



report date: 2024-03-29


Internet history


Entry 1

Date 2021-07-25
Pictures 3

Listing price <u>View report</u>







source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT #18	2020-11-28 18:51

MOT test number 798605709951

Next expiry date 2021-11-27

MOT #17 2020-11-28 18:51

MOT test number 901476820186

Result X Failed

Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

MOT #16 2019-05-10 08:12

MOT test number 595074013950

Result \rightarrow Passed

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #15 2018-04-24 12:47

MOT test number 765330945734

Advice Front brake pads low

CarCheck.co.uk page 3/14



Fail

Fail

CE55XBY

report date: 2024-03-29

MOT test number

956741464589

Result

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Fail Offside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Front brake pads low

Fail Offside Stop lamp not working (1.2.1b)

Offside Front position lamp(s) not working (1.1.A.3b)

Offside Rear position lamp(s) not working (1.1.A.3b)

MOT #13

MOT test number

498321430510

Result

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice N/S Wing mirror loose

Advice Brake pad(s) wearing thin Both front (3.5.1g)

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #12 2017-03-28 11:18

MOT test number 941184285299

Result X Failed

Fail Nearside Front Headlamp not working on dipped beam (1.7.5a)

Advice N/S Wing mirror loose

Advice Brake pad(s) wearing thin Both front (3.5.1g)

Fail Nearside Front Lower Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Offside Front Headlamp aim too high (1.8)

Fail Battery insecure (1.9.1)

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Fail Parking brake: efficiency below requirements (3.7.C.1b)

Fail Central Front registration plate delaminated (6.3.1d)

MOT #11 2016-02-05 16:48

MOT test number 761477332741

Advice Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)

Advice Offside Rear Fuel hose slightly damaged (7.2.2)

Advice Offside Front Brake hose slightly deteriorated (3.6.B.4d)

Advice Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt

(2.5.C.1a)

Advice Nearside Front Brake hose slightly deteriorated (3.6.B.4d)

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #10 2016-02-05 16:48 **MOT** test number 884761134019 Result × Failed **Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d) Advice Offside Front Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a) **Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d) Nearside Rear Brake hose slightly deteriorated (3.6.B.4d) Advice **Advice** Offside Rear Fuel hose slightly damaged (7.2.2)

MOT #9

MOT test number

Result

2015-02-12 17:00

488213245072

✓ Passed

MOT #8 2014-02-12 12:05
MOT test number 277823344088

Nesuit V 1 d3

Advice Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)

Notice Under-trays fitted obscuring some underside components

MOT #7 2013-02-15 13:29

MOT test number 617236243000

Result ✓ Passed

CarCheck.co.uk page 6/14



CE55XBY report date: 2024-03-29

MOT #6 2013-02-15 09:34

MOT test number 116386743098

Result X Failed

Pass with rectification Nearside Headlamp not working on dipped beam (1.7.5a)

Fail Nearside Rear Brake hose excessively damaged (3.6.B.4d)

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #5 2012-01-04 10:19

MOT test number 887324902087

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #4 2011-01-04 11:57

MOT test number 116724201026

Result ✓ Passed

MOT #3 2010-01-05 14:03

MOT test number 541065500019

Result
✓ Passed

MOT #2 2008-12-12 16:04

MOT test number 712147948359

Result \(\sqrt{Passed} \)

Advice Offside Outer Track rod end ball joint has slight play (2.2.B.1f)

CarCheck.co.uk page 7/14



report date: 2024-03-29

2008-12-12 09:44 **MOT #1**

MOT test number 412287348452

Result **★** Failed **Advice** Offside Outer Track rod end ball joint has slight play (2.2.B.1f) Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) Fail Nearside Headlamp not working on dipped beam (1.7.5a) Fail Offside Stop lamp not working (1.2.1b) Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) Nearside Headlamp aim not tested (1.8.A.1c) Fail Fail Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

o micr mistory	
For how long did the current and previous owner(s) have this LAND ROVER? How many o ROVER have? Check it in the premium report and see all owner registrations. Download to	

	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	
Current registration	NK NE
Plate since	
Current registration	NK WE
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-11-24
Last registration	2020-11-28
Complete history	See info



Registration #1	2005-11-24	9 mi
Registration #2	2008-12-12	32.415 mi
Registration #3	2008-12-12	32.416 mi
Registration #4	2010-01-05	51.403 mi
Registration #5	2011-01-04	74.497 mi
Registration #6	2012-01-04	98.926 mi
Registration #7	2013-02-15	110.216 mi
Registration #8	2013-02-15	110.216 mi
Registration #9	2014-02-12	122.866 mi
Registration #10	2015-02-12	145.222 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		77.777 es

More info >

CarCheck.co.uk page 13/14



CE55XBY report date: 2024-03-29

Safety ratings

NCAP i	rating	****
IICAI I	acing	~~~~

Video <u>see crash video</u>



Dimensions & weight

Width	2071 mm
Kerb weight	1515 kg
Max. allowed weight	2050 kg

Additional information

Number of seats	3
Number of axles	2
Engine number	81376065

CarCheck.co.uk page 14/14