





report date: 2024-03-29

# General information

Make	MERCEDES-BENZ
Model	ML ML350 BLUETEC SPORT
Colour	Silver
Year of manufacture	2012
Top speed	139 mph
0 - 100 km/h	7.4 seconds
0 - 60 mph	7.4 seconds
Gearbox	7 speed automatic

# Engine & fuel consumption

Power	190 kW / 259 HP / 258 BHP
Max. torque	620 Nm at 1.600 rpm
Engine capacity	2.987 сс
Cylinders	6
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	42.2 mpg
Consumption combined	39.2 mpg
CO2 emission	189 g/km
CO2 label	J



CarCheck.co.uk page 1/13



# Internet history

# Entry 1


Date 2021-09-16

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-11-09
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	21
Total items failed	6

MOT #12	2023-10-17 07:21
MOT test number	940032765390
Result	<b>✓</b> Passed
Next expiry date	2024-11-09

MOT #11	. 20	022-11-10 14:34
MOT test	number	936102661170
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 (k	o) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))		movement
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 (b)	(i))

CarCheck.co.uk page 3/13



YH12HXF

report date: 2024-03-29

2022-11-07 12:47 **MOT #10** 600300529942 **MOT** test number Result × Failed **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i)) Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i)) Fail **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Rear Suspension rod corroded and seriously weakened (5.3.3 (b) (i)) Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) Fail **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Rear Suspension rod corroded and seriously weakened (5.3.3 (b) (i)) Fail

MOT #9	2021-10-27 12:15
MOT test number	799947740675
Result	<b>✓</b> Passed
	****
MOT #8	2021-06-11 11:03
MOT test number	366554921142
Result	✓ Passed
Advice Slight oil leak on engine	

MOT #7	2020-06-11 09:04
MOT test number	661683288220
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/13



MOT #6 2019-07-11 15:21

MOT test number 466691744179

**Result** ✓ Passed

**Advice** Rear Child Seat fitted not allowing full inspection of adult belt x2

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge CLOSE TO LIMIT (5.2.3 (e))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2018-07-04 16:07

MOT test number 776694788583

Result \square Passed

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Oil leak

MOT #4 2017-07-17 15:34

**MOT test number** 842885949472

**Result** 
✓ Passed

Advice Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt leaking grease but not ripped/split (2.5.C.1a)

MOT #3 2016-07-11 11:39

MOT test number 598392902229

**Result** ✓ Passed

**Advice** Brake pad(s) wearing thin front and rear (3.5.1g)

MOT #2 2015-06-25 10:22

**MOT test number** 535736975112

Result 

Passed


**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



YH12HXF

report date: 2024-03-29



CarCheck.co.uk page 6/13



# Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	9 November 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	49
Venicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1

Date

Category
Type

Damage 2

Date

Category
Type



#### Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



More info >

# Owner history

,	
For how long did the current and previous owner(s) have this MERCEDES-BENZ? How man MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Export here.	
***************************************	
********	
	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	IK SIE
Plate since	
Current registration	器 UK
Plate since	

CarCheck.co.uk page 10/13



### Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-06-30
Last registration	2023-10-17
Complete history	See info



Registration #1	2012-06-30	17 mi
Registration #2	2015-06-25	22.560 mi
Registration #3	2016-07-11	30.355 mi
Registration #4	2017-07-17	36.564 mi
Registration #5	2018-07-04	42.845 mi
Registration #6	2019-07-11	48.068 mi
Registration #7	2020-06-11	50.896 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		0.77 66

More info >

CarCheck.co.uk page 12/13



#### Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225 Air conditioning

**S0295** 

**S0482** 

**S0501** 

**S0566** 

**S0567** 

**S0569** 

View the complete MERCEDES-BENZ factory list for this vehicle <u>here</u>.

More info >

### Safety ratings

NCAP rating
-------------

**Video** <u>see crash video</u>



# Dimensions & weight

Width	1998 mm
Height	1796 mm
Length	4804 mm
Wheel base	2915 mm
Kerb weight	2175 kg
Max. allowed weight	2950 kg

# Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of doors	3

CarCheck.co.uk page 13/13

Number of seats	5
Number of axles	2
Engine number	64282641326799