



report date: 2024-03-28

General information

Make	VAUXHALL
Model	CROSSLAND SE ECOTEC S/S
Colour	Silver
Year of manufacture	2019
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	68.9 mpg
Consumption extra urban	85.6 mpg
Consumption combined	78.5 mpg
CO2 emission	93 g/km
CO2 label	A





Internet history

Entry 2

Date	2022-04-25
Pictures	1
Listing price	View report



source: yesauto.com

Entry 1

Date	2022-04-23
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-18
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	14
Total items failed	1

MOT #5	2024-04-19 08:16
MOT test number	352703727284
Result	✓ Passed
Next expiry date	2025-04-18
Advice	Coolant low
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4	2023-04-04 08:40
MOT test number	904351677943
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 195/60/16 (5.2.3 (e))

**MOT #3** 2023-04-04 08:40**MOT test number** 271343965549**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 195/60/16 (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Headlamp aim too low (4.1.2 (a))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #2** 2022-05-17 07:26**MOT test number** 235694672754**Result** ✗ Failed**MAJOR** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Boot not opening**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (iii))**MOT #1** 2022-03-11 10:22**MOT test number** 327335404775**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
18 April 2025

Tax status	Valid until 1 June
Days left	34
MOT expiry date	18 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
First licence fee (12 months)	£ 165,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 BF19SYV
Plate since	2019-06-29
Current registration	 BF19SYV
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2019-03-29
Last registration	2024-04-19
Complete history	See info



Registration #1	2019-03-29	7 mi
Registration #2	2022-03-11	16.537 mi
Registration #3	2019-03-29	25.277 mi
Registration #4	2019-03-29	25.277 mi
Registration #5	2019-03-29	25.277 mi
Registration #6	2019-03-29	25.277 mi
Registration #7	2019-03-29	25.277 mi
Registration #8	2019-03-29	25.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	85%
Children	84%
Pedestrian	62%
Safety systems	57%
Overall rating	75%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1605 mm
Length	4212 mm
Max. allowed weight	1820 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	10JBHT0056615 LEK