

Ford



General information

Make	FORD
Model	FIESTA EDGE TDCI
Colour	Black
Year of manufacture	-
Top speed	101 mph
0 - 60 mph	14.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	67.3 mpg





Internet history

Entry	1	
Date		

Pictures

2021-01-30

10

Listing price

View report



source: autoonline.co.uk



MOT history

MOT #11	2022-02-03 11:09
MOT test number	116390526610
Result	🗙 Failed
Advice Coil spring corroded both rear coil springs corroded (5.3.1 (b) (i)) Fail (ii)) Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ing	ress of dirt (5.3.4 (b)
Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail Exhaust has a major leak of exhaust gases exhaust back box corroded holed and	l leaking (6.1.2 (a))

MOT #10	2020-12-24 11:58
MOT test number	634370906628
Result	✓ Passed
MOT #9	2020-01-10 15:28
MOT test number	268396819569
Result	✓ Passed
MOT #8	2019-03-26 13:14
MOT test number	946757973731
Result	✓ Passed
MOT #7	2018-03-22 11:08
MOT test number	472786855916
Result	✓ Passed
MOT #6	2017-04-06 14:12
MOT test number	788603516046
Result	✓ Passed





MOT #5	2017-04-01 10:11
MOT test number	199953901455
Result	🗙 Failed
Fail Offside Front coil spring broken (2.4.C.1a)	
MOT #4	2016-03-26 10:06
MOT test number	241282460641
Result	✓ Passed
MOT #3	2015-03-28 09:34
MOT test number	179837085406
Result	✓ Passed
MOT #2	2014-03-22 13:11
MOT test number	969691684026
Result	✓ Passed
MOT #1	2013-04-20 10:22
MOT test number	569190113193
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-05-29
Last registration	2022-02-03
Complete history	See info



Registration #1	2010-05-29	20 mi
Registration #2	2013-04-20	22.875 mi
Registration #3	2014-03-22	28.161 mi
Registration #4	2015-03-28	34.065 mi
Registration #5	2016-03-26	41.430 mi
Registration #6	2017-04-01	47.532 mi
Registration #7	2017-04-06	47.532 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.117 mi





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1973 mm
Height	1481 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1086 kg
Max. allowed weight	1535 kg
Additional information	
Fuel tank capacity	40
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 10/10

Number of axles	2
Engine number	9D85410