



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	407 HDI SE
Colour	Black
Year of manufacture	-
Top speed	129 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.9 mpg



LABEL UNKNOWN

**MOT history****MOT #16** 2020-10-16 07:52**MOT test number** 843276692858**Result** ✓ Passed**Next expiry date** 2021-10-15

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #15** 2020-10-14 12:31**MOT test number** 727426121181**Result** ✗ Failed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #14** 2019-10-02 09:32**MOT test number** 330808544711**Result** ✓ Passed**MOT #13** 2018-10-10 10:50**MOT test number** 553949658653**Result** ✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2017-10-10 11:04**MOT test number** 313180148902**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Oil leak**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #11** 2016-10-13 08:24**MOT test number** 408239113144**Result** ✓ Passed**MOT #10** 2016-02-17 14:56**MOT test number** 690827264370**Result** ✓ Passed**MOT #9** 2016-02-16 14:51**MOT test number** 179928737113**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #8** 2015-02-13 09:57**MOT test number** 199694345460**Result** ✓ Passed**MOT #7** 2013-12-05 13:49**MOT test number** 425229133405**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2012-11-03 08:41**MOT test number** 157028202313**Result** ✓ Passed**MOT #5** 2011-09-27 16:00**MOT test number** 237270271247**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-09-27 10:37**MOT test number** 655380871209**Result** ✗ Failed**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-09-28 10:01**MOT test number** 383431870278**Result** ✓ Passed

**MOT #2** 2009-10-01 16:18**MOT test number** 763044079268**Result** ✓ Passed

- Notice** Brake fluid level slightly high
- Notice** Offside tyre has cuts in tread no ply and cords exposed
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Nearside front headlamp slightly dim
- Notice** Undertray and offside front wheel arch trim damaged

**MOT #1** 2009-10-01 16:18**MOT test number** 734244579272**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Brake fluid level slightly high
- Notice** Offside tyre has cuts in tread no ply and cords exposed
- Pass with rectification** Nearside Front Brake hose has insufficient room to move, resulting in fouling on any part (3.6.B.4a)
- Notice** Nearside front headlamp slightly dim
- Notice** Undertray and offside front wheel arch trim damaged



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-09-30
Last registration	2020-10-16
Complete history	<a href="#">See info</a>



Registration #1	2006-09-30	7 mi
Registration #2	2009-10-01	32.730 mi
Registration #3	2010-09-28	42.246 mi
Registration #4	2011-09-27	48.745 mi
Registration #5	2011-09-27	48.745 mi
Registration #6	2012-11-03	56.022 mi
Registration #7	2013-12-05	60.754 mi
Registration #8	2015-02-13	67.700 mi
Registration #9	2016-05-20	75.277 mi
Registration #10	2017-05-20	83.277 mi
Registration #11	2018-05-20	91.277 mi
Registration #12	2019-05-20	99.277 mi
Registration #13	2020-05-20	107.277 mi
Registration #14	2021-05-20	115.277 mi
Registration #15	2022-05-20	123.277 mi
Registration #16	2023-05-20	131.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1811 mm
Height	1445 mm
Length	4676 mm
Wheel base	2725 mm
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2

**Engine number**

DYUK4013967