



BL65CVM


report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI STARTLINE
Colour	White
Year of manufacture	2015
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	250 Nm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	67.3 mpg
Consumption combined	60.1 mpg
CO2 emission	123 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-11-25
Pictures	43
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-08
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	11
Total items failed	0

MOT #8	2023-08-02 15:58
MOT test number	199915658977
Result	✓ Passed
Next expiry date	2024-08-08
Advice	Front Tyre worn close to legal limit/worn on edge Both inner edge's are wearing off 195/65/15 95T (5.2.3 (e))

MOT #7	2022-07-29 13:33
MOT test number	820830060261
Result	✓ Passed

MOT #6	2021-08-09 09:18
MOT test number	357022858499
Result	✓ Passed

MOT #5	2020-12-16 11:43
MOT test number	636881044626
Result	✓ Passed

**MOT #4** 2020-12-15 15:50**MOT test number** 886641007882**Result** ✗ Failed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**DANGEROUS** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**DANGEROUS** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #3** 2020-11-18 13:16**MOT test number** 809056817750**Result** ✗ Failed**MAJOR** Supplementary restraint system warning lamp indicates a fault airbag (7.1.6 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))**Advice** Nearside Rear Lamp unit has slight damage to the lens.**MAJOR** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #2** 2019-12-04 13:43**MOT test number** 949978227667**Result** ✓ Passed**MOT #1** 2018-11-19 16:53**MOT test number** 979274626398**Result** ✓ Passed**Advice** Offside Rear Lamp unit has slight damage to the lens.**Advice** Nearside Rear Lamp unit has slight damage to the lens.



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
8 August 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	8 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-12-04
Last registration	2023-08-02
Complete history	See info



Registration #1	2015-12-04	20 mi
Registration #2	2018-11-19	51.060 mi
Registration #3	2019-12-04	68.887 mi
Registration #4	2020-11-18	76.889 mi
Registration #5	2020-12-15	76.899 mi
Registration #6	2020-12-15	76.899 mi
Registration #7	2020-12-15	76.899 mi
Registration #8	2020-12-15	76.899 mi
Registration #9	2020-12-15	76.899 mi
Registration #10	2020-12-15	76.899 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	78%
Pedestrian	58%
Safety systems	68%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	2062 mm
Height	1836 mm
Length	4876 mm
Kerb weight	1565 kg
Max. allowed weight	2299 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	DFSD051843