





report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Blue
Year of manufacture	2008
Top speed	129 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Sequential

Engine & fuel consumption

Power	145 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	184 g/km
CO2 label	I



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-01-31

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



RX08RHE report date: 2024-03-29

MOT history

MOT expiry date	2025-02-04
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	15
Total items failed	0

MOT #17	202	4-02-05 16:57
MOT test	number 6	76708282000
Result		✓ Passed
Next expi	iry date	2025-02-04
Advice	Both rear tyres worn on inner edges	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))		i))
Advice	Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b)	(i))

MOT #16		2024-01-31 15:20
MOT test	number	849371200930
Result		× Failed
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
MAJOR	Offside Rear Lower Suspension arm corroded and seriously weakened (5	5.3.3 (b) (i))
Advice	Nearside Rear Lower Suspension arm corroded but not seriously weaker	ned (5.3.3 (b) (i))
MAJOR Offside Rear Lower Suspension spring mounting prescribed area excessively corroded significantly reducing structural strength Arm (5.3.6 (a) (i))		
Advice	Both rear tyres worn on inner edges	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened Both	n (1.1.14 (a) (ii))

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #15 2023-02-01 17:00

MOT test number 997598674969

Result
✓ Passed

MOT #14 2021-11-12 17:10

MOT test number 797932213810

Result

✓ Passed

MOT #13 2020-09-23 09:39

MOT test number 499023742848

Result \(\sqrt{Passed} \)

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #12 2019-05-03 14:39

MOT test number 325956807993

Result \(\sqrt{Passed} \)

MOT #11 2019-05-03 11:06

MOT test number 501341489487

Result X Failed

MAJOR Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #10 2018-04-28 14:07

MOT test number 548656115735

CarCheck.co.uk page 4/13



MOT #9

MOT #5

RX08RHE

report date: 2024-03-29

2017-03-16 12:06

2014-02-20 15:19

MOT test r	number	791677756027
Result		✓ Passed
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)	
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)	
MOT #8		2016-04-05 10:50
MOT test r	number	715197668275
Result		✓ Passed
MOT #7		2015-04-10 16:06
MOT test r	number	866950405182
Result		✓ Passed
MOT #6		2015-02-12 14:08
MOT test r	number	278003445043
Result		✓ Passed

MOT test number	127701354453
Result	✓ Passed

MOT #4	2013-08-16 09:38
MOT test number	996958323280
Result	✓ Passed

MOT #3	2013-05-31 10:29
MOT test number	665681253172
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #2	2012-05-28 10:26
MOT test number	207129742433
Result	✓ Passed
MOT #1	2011-06-07 11:34
MOT test number	528368651101

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	4 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	T
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



RX08RHE report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



RX08RHE report date: 2024-03-29

Owner history

e when miscory		
For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		R
THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this JAGUAR had different number plates.		
Number of plates		,
Current registration	NK NA	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-07-21
Last registration	2024-02-05
Complete history	See info



Registration #1	2008-07-21	14 mi
Registration #2	2011-06-07	14.145 mi
Registration #3	2012-05-28	17.918 mi
Registration #4	2013-05-31	20.726 mi
Registration #5	2013-08-16	21.851 mi
Registration #6	2014-02-20	21.873 mi
Registration #7	2015-02-12	31.686 mi
Registration #8	2015-04-10	32.923 mi
Registration #9	2016-04-05	36.409 mi
Registration #10	2017-03-16	38.272 mi
Registration #11		71.777 66
Registration #12		77.777 46
Registration #13		71.777 es
Registration #14		71.777 es
Registration #15		71.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1395 mm
Length	4672 mm
Wheel base	2710 mm
Max. allowed weight	2065 kg

Additional information

Fuel tank capacity	61 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	080212203227BG

CarCheck.co.uk page 13/13