





report date: 2024-03-28

### General information

Make	MERCEDES
Model	SL SL 350
Colour	Black
Year of manufacture	2006
Top speed	155 mph
0 - 60 mph	6.6 seconds
Gearbox	7 speed automatic

# Engine & fuel consumption

Power	272 BHP
Max. torque	350 Nm at 2.400 rpm
Engine capacity	3.498 сс
Cylinders	6
Fuel type	Petrol
Consumption city	19.1 mpg
Consumption extra urban	36.7 mpg
Consumption combined	27.4 mpg
CO2 emission	246 g/km
CO2 label	L



CarCheck.co.uk page 1/13



LL56EPC

report date: 2024-03-28


# Internet history

### Entry 2


Date 2021-10-11

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-08-03
Pictures	13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



2022-03-08 09:51

MOT history

MOT #14

MOT expiry date	2025-03-07
MOT pass rate	94 %
MOT passed	15
Failed MOT tests	1
Total advice items	31
Total items failed	0

MOT #16	2024-03-05 12:43
MOT test number	152929298830
Result	✓ Passed
Next expiry date	2025-03-07

MOT #15	2023-03-06 14:20
MOT test number	236880317826
Result	<b>✓</b> Passed
Minor  (b) (i))  Nearside Registration plate lamp inoperative in the case of multiple lamp	ps or light sources (4.7.1
Advice Nearside Front Upper Suspension arm ball joint has slight play (5.3.4 (a	) (i))
Advice Suspension squeaks	

MOT test number	672830954297
Result	✓ Passed
MOT #13	2021-04-28 11:54
MOT test number	153570037205
Result	✓ Passed
Advice Parking brake efficiency only just met (16%).	
Advice Covers fitted obscuring some components.	

CarCheck.co.uk page 3/13



LL56EPC

report date: 2024-03-28

**MOT #12** 2020-05-01 15:09

**MOT test number** 748299299825

**MOT #11** 2020-05-01 08:20

**MOT test number** 223331738143

**Result** ★ Failed

MAJOR Brake servo defective or ineffective no servo efficiency felt (1.1.10 (a) (i))

**DANGEROUS** Offside Front Brake pipe connection leaking on a hydraulic braking system pipe to hose joint wet wiped and checked under pressure looked like very slight seepage starting? (1.1.11 (b) (ii))

MOT #10 2019-01-18 13:10

**MOT test number** 401502680569

**Result** 
✓ Passed

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #9 2018-01-20 12:43

MOT test number 535812537306

Result / Passed

**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Front Torque/reaction arm has a slightly deteriorated rubber bush (2.4.G.2)

**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

**Advice** Offside Front Torque/reaction arm has a slightly deteriorated rubber bush (2.4.G.2)

CarCheck.co.uk page 4/13



Passed

**MOT #8** 2017-01-07 10:10

**MOT test number** 783212094301

**Result** ✓ Passed

**Advice** Nearside Front Torque/reaction arm has a slightly deteriorated rubber bush (2.4.G.2)

**Advice** Offside Front Torque/reaction arm has a slightly deteriorated rubber bush (2.4.G.2)

MOT #7 2015-12-12 11:16

MOT test number 209201837745

**Result** 
✓ Passed

**Advice** Small cracks in all tyre treads

Result

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2014-12-06 09:47

MOT test number 675200844363

Advice Offside Front Torque/reaction arm has a slightly deteriorated rubber bush (2.4.G.2)

**Advice** Nearside Front Torque/reaction arm has a slightly deteriorated rubber bush (2.4.G.2)

MOT #5 2013-12-19 10:05

**MOT test number** 789503453336

**Result** ✓ Passed

MOT #4 2012-11-27 11:57

MOT test number 827072132356

Result / Passed

**Advice** Parking brake lever has little reserve travel (3.1.6b)

CarCheck.co.uk page 5/13



Result

LL56EPC report date: 2024-03-28

✓ Passed

MOT #3 2011-12-20 09:19
MOT test number 366064651351

Result ✓ Passed

**Notice** Both front tyres wearing on the edges

 MOT #2
 2010-10-26 14:28

 MOT test number
 180389790292

**MOT #1** 2009-10-28 10:53

MOT test number 553831209390

**Notice** 2 emission sheets printed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Rear rear brake juddering slightly (3.7.A.5b)

**Notice** Large under trays and nearside slight damaged

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**Advice** Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Offside head/light aim on upper limit/

CarCheck.co.uk page 6/13



# Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	7 March 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 7/13



### Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <a href="here">here</a> for the results.

### Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	
Туре	



### Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.	
********	
***************************************	
***************************************	
***************************************	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	IK NE
Plate since	
	More info >

CarCheck.co.uk page 10/13



### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



# Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-11-01
Last registration	2024-03-05
Complete history	See info



Registration #1	2006-11-01	10 mi
Registration #2	2009-10-28	50.275 mi
Registration #3	2010-10-26	64.355 mi
Registration #4	2011-12-20	79.095 mi
Registration #5	2012-11-27	91.357 mi
Registration #6	2013-12-19	104.442 mi
Registration #7	2014-12-06	106.412 mi
Registration #8	2015-12-12	108.048 mi
Registration #9	2017-01-07	109.742 mi
Registration #10	2018-01-20	112.331 mi
Registration #11		71.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		0.777 es

More info >

CarCheck.co.uk page 12/13



# Dimensions & weight

Width	2033 mm
Height	1317 mm
Length	4532 mm
Wheel base	2560 mm
Kerb weight	1825 kg
Max. allowed weight	2120 kg

# Additional information

Fuel tank capacity	88 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27296630518763

CarCheck.co.uk page 13/13