





report date: 2024-03-28

General information

Make	TOYOTA
Model	ESTIMA
Colour	Grey
Year of manufacture	2007
Gearbox	-

Engine & fuel consumption

Engine capacity	2.360 cc
Fuel type	Petrol



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-10-28

Pictures 32

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



LK570RP

report date: 2024-03-28

MOT history

MOT expiry date	2024-10-03
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	13
Total items failed	1

MOT #9		2023-10-04 10:56
MOT test	number	499819091295
Result		✓ Passed
Next expi	ry date	2024-10-03
Advice Nearside Front Anti-roll bar damaged but not seriously weakened (5.3.3 (b) (i))		
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #8	2022-10-12 12:26
MOT test number	408321251600
Result	✓ Passed
Advice Rear Direction indicator slightly discoloured (4.4.3 (a))	

MOT #7		2021-10-26 15:25
MOT test number		690536148479
Result		✓ Passed
MOT #6		2021-10-26 15:24
MOT test number		635637140780
Result		X Failed
Pass with rectification	Headlamp aim too low (4.1.2 (a))	

CarCheck.co.uk page 3/11



LK57ORP

report date: 2024-03-28

MOT #5 2020-11-11 13:00

MOT test number 875273172389

Result ✓ Passed

MOT #4 2020-11-06 13:08

MOT test number 833153297416

Result X Failed

MAJOR Nearside Rear Sub-frame pin or bush excessively worn (5.3.4 (a) (i))

MAJOR Spare wheel insecure in carrier (6.1.5 (b) (i))

MAJOR Offside Rear Sub-frame pin or bush excessively worn (5.3.4 (a) (i))

MOT #3 2019-11-06 10:03

MOT test number 418590119473

Result \rightarrow Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2019-11-05 15:13

MOT test number 118669324358

Result × Failed

DANGEROUS Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

DANGEROUS Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



MOT #1 2018-11-10 10:17

MOT test number 522187408548

Result ✓ Passed

CarCheck.co.uk page 5/11



Tax & MOT check



Days left 186

MOT expiry date 3 October 2024

Full MOT history See MOT history

CarCheck.co.uk page 6/11



LK570RP

report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full r)TA

	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



LK570RP

report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2007-07-01
Last registration	2023-10-04
Complete history	See info



Registration #1	2007-07-01	28 mi
Registration #2	2018-11-10	75.669 mi
Registration #3	2019-11-05	79.889 mi
Registration #4	2019-11-06	79.889 mi
Registration #5	2020-11-06	84.601 mi
Registration #6	2020-11-11	84.608 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		D.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Additional information

Number of seats	8
Engine number	NOT KNOWN

CarCheck.co.uk page 11/11