



report date: 2024-03-28

General information

Make	CITROEN
Model	NEMO HDI 8V
Colour	Red
Year of manufacture	2010
Top speed	94 mph
0 - 60 mph	18.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C







Internet history

Entry 1

Date	2022-01-31
Pictures	47
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-12
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	27
Total items failed	5

MOT #172024-04-11 15:50

MOT test number205460154005

Result✓ Passed

Next expiry date2025-04-12

- Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Rear Exhaust mounting rubber splitting / worn
- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Minor

Offside Windscreen wiper blade defective Slightly smearing (3.4 (b) (i))
- Advice

Offside Front Suspension top mount / bearing rough on rotation
- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice

Oil leak, but not excessive Engine (8.4.1 (a) (i))
- Advice

Lower Gearbox mounting defective Splitting / worn
- Advice

Nearside Front Suspension top mount / bearing rough on rotation

**MOT #16**

2024-04-11 10:35

**MOT test number**

109071585019

**Result****✗ Failed**

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive Engine (8.4.1 (a) (i))
- Advice** Nearside Front Suspension top mount / bearing rough on rotation
- Advice** Lower Gearbox mounting defective Splitting / worn
- Minor** Offside Windscreen wiper blade defective Slightly smearing (3.4 (b) (i))
- Advice** Rear Exhaust mounting rubber splitting / worn
- Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))
- Advice** Offside Front Suspension top mount / bearing rough on rotation
- Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #15**

2023-04-12 14:52

**MOT test number**

828596360292

**Result****✓ Passed**

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing cracked/split in tread (5.2.3 (d) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**MOT #14** 2022-04-13 15:42**MOT test number** 613834618208**Result** ✓ Passed**Advice** Rear Coil spring corroded both side (5.3.1 (b) (i))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**MOT #13** 2021-06-18 15:23**MOT test number** 214494734459**Result** ✓ Passed**MOT #12** 2021-06-18 14:05**MOT test number** 576130316361**Result** ✗ Failed**Fail** Front Brakes imbalanced across an axle (1.2.1 (b) (i))**MOT #11** 2020-07-20 11:51**MOT test number** 727881407824**Result** ✓ Passed**MOT #10** 2019-10-28 13:39**MOT test number** 239010116720**Result** ✓ Passed**MOT #9** 2018-10-25 09:57**MOT test number** 694807136701**Result** ✓ Passed**MOT #8** 2017-10-25 11:32**MOT test number** 236963627918**Result** ✓ Passed

**MOT #7** 2017-10-25 10:03**MOT test number** 927736401906**Result** ✗ Failed**Fail** Nearside Macpherson strut has excessive movement in the upper support bearing assembly (2.5.B.1b)**Fail** Offside Macpherson strut has excessive movement in the upper support bearing assembly (2.5.B.1b)**MOT #6** 2016-11-01 10:32**MOT test number** 474259123496**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre 185/65 15**Advice** Oil leak**MOT #5** 2015-11-03 09:34**MOT test number** 540379732141**Result** ✓ Passed**MOT #4** 2014-11-03 11:23**MOT test number** 565347404330**Result** ✓ Passed**MOT #3** 2014-04-17 09:53**MOT test number** 385347004169**Result** ✓ Passed**Notice** Offside rear tyre is perished**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-04-22 15:22**MOT test number** 818002213148**Result** ✓ Passed



MOT #1	2012-11-30 12:07
MOT test number	467475932409
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
12 April 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	12 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-01-14
Last registration	2024-04-11
Complete history	<a href="#">See info</a>



Registration #1	2010-01-14	13 mi
Registration #2	2012-11-30	18.837 mi
Registration #3	2013-04-22	19.803 mi
Registration #4	2014-04-17	38.201 mi
Registration #5	2014-11-03	41.358 mi
Registration #6	2015-11-03	53.099 mi
Registration #7	2016-11-01	65.144 mi
Registration #8	2017-10-25	74.769 mi
Registration #9	2017-10-25	74.769 mi
Registration #10	2018-10-25	77.729 mi
Registration #11	2019-05-29	81.377 mi
Registration #12	2019-05-29	81.377 mi
Registration #13	2019-05-29	81.377 mi
Registration #14	2019-05-29	81.377 mi
Registration #15	2019-05-29	81.377 mi
Registration #16	2019-05-29	81.377 mi
Registration #17	2019-05-29	81.377 mi
Registration #18	2019-05-29	81.377 mi
Registration #19	2019-05-29	81.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	59%
Children	74%
Pedestrian	55%
Safety systems	29%
Overall rating	58%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1816 mm
Height	1721 mm
Length	3959 mm
Wheel base	2513 mm
Kerb weight	1185 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FD982641028