




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT S TDI BLUEMOTION TECHNOLOGY
Colour	Silver
Year of manufacture	2015
Top speed	127 mph
0 - 100 km/h	11.0 seconds
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	88 kW / 120 HP / 118 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	76.3 mpg
Consumption combined	68.9 mpg
CO2 emission	107 g/km
CO2 label	B





## Internet history

### Entry 2

Date	2022-10-30
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

### Entry 1

Date	2021-02-06
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-01-10
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	12
Total items failed	4

MOT #8	2023-12-27 10:04
MOT test number	290623620444
Result	✓ Passed
Next expiry date	2025-01-10
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both ns/os (1.1.14 (a) (ii))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7	2023-01-11 14:55
MOT test number	152292560266
Result	✓ Passed
Advice	Brake disc worn, pitted or scored, but not seriously weakened both front discs worn/pitted on inside faces (1.1.14 (a) (ii))
Advice	O/s daytime running light n/w

**MOT #6**

2023-01-04 12:54

**MOT test number**

391232161680

**Result****✗ Failed****Advice** O/s daytime running light n/w**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Undertray likely to become detached engine undertray loose (6.2.1 (a) (ii))**Fail** Registration plate does not conform to the specified requirements both number plates have darkened backgrounds (0.1 (d))**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front discs worn/pitted on inside faces (1.1.14 (a) (ii))**MOT #5**

2021-09-03 14:29

**MOT test number**

892342172499

**Result****✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4**

2020-08-04 12:00

**MOT test number**

726717844734

**Result****✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge tyre wearing on inner edge (5.2.3 (e))**Advice** Both rear tyres feathering on inner edge**Advice** Offside Front Tyre worn close to legal limit/worn on edge tyre getting low on tread also wearing on inner edge (5.2.3 (e))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #3**

2019-06-05 11:29

**MOT test number**

266175551381

**Result****✓ Passed**



MOT #2	2018-06-07 10:11
MOT test number	631116364966
Result	✓ Passed

MOT #1	2018-06-07 10:11
MOT test number	562989728231
Result	✗ Failed

Pass with rectification

 Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
10 January 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	10 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>VE15YVX</b>
Plate since	2015-05-29
Current registration	 <b>VE15YVX</b>
Plate since	2015-05-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-06-19
Last registration	2023-12-27
Complete history	<a href="#">See info</a>



Registration #1	2015-06-19	10 mi
Registration #2	2018-06-07	74.013 mi
Registration #3	2018-06-07	74.013 mi
Registration #4	2019-06-05	92.705 mi
Registration #5	2020-08-04	113.660 mi
Registration #6	2020-08-04	113.660 mi
Registration #7	2020-08-04	113.660 mi
Registration #8	2020-08-04	113.660 mi
Registration #9	2020-08-04	113.660 mi
Registration #10	2020-08-04	113.660 mi
Registration #11	2020-08-04	113.660 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	85%
Children	87%
Pedestrian	66%
Safety systems	76%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1820 mm
Height	1516 mm
Length	4771 mm
Wheel base	2712 mm
Kerb weight	1400 kg
Max. allowed weight	2060 kg

Additional information

Fuel tank capacity	59 l
Fuel delivery	Direct Injection
Number of doors	5

Number of axles	2
Engine number	DCXA009039