



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOUAREG V6 ALTITUDE TDI
Colour	Black
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	550 Nm at 2.000 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	21.7 mpg
Consumption extra urban	34.9 mpg
Consumption combined	28.5 mpg
CO2 emission	244 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-06-04
Pictures	38
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-24
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	16
Total items failed	7

MOT #15 2023-07-25 15:43**MOT test number** 100240117813**Result** ✓ Passed**Next expiry date** 2024-07-24**Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer sill corroded (5.3.6 (a) (i))**Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer sill corroded (5.3.6 (a) (i))**MOT #14** 2023-07-13 12:31**MOT test number** 231108587355**Result** ✗ Failed**Fail** Central Rear Seat belt not functioning as intended (7.1.2 (c))**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer sill corroded (5.3.6 (a) (i))**Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer sill corroded (5.3.6 (a) (i))**Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #13** 2022-07-19 16:33**MOT test number** 120608896909**Result** ✓ Passed**Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 275/40/ZR20 (5.2.3 (e))**Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**MOT #12** 2022-07-13 16:32**MOT test number** 625257530010**Result** ✗ Failed**Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**Fail** Central Rear Seat belt not functioning as intended (7.1.2 (c))**Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Fail** Front Windscreen washer not working (3.5 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 275/40/ZR20 (5.2.3 (e))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #11** 2021-07-16 12:25**MOT test number** 352807273773**Result** ✓ Passed**MOT #10** 2020-11-17 10:02**MOT test number** 144021698098**Result** ✓ Passed



MOT #9	2019-07-15 16:58
MOT test number	719190962905
Result	✓ Passed
MOT #8	2018-02-13 17:43
MOT test number	878259628993
Result	✓ Passed
MOT #7	2017-03-01 17:32
MOT test number	973003754196
Result	✓ Passed
MOT #6	2016-02-01 16:22
MOT test number	397938438855
Result	✓ Passed
MOT #5	2015-09-22 10:39
MOT test number	620307799157
Result	✓ Passed
MOT #4	2014-10-08 16:32
MOT test number	527301884282
Result	✓ Passed
MOT #3	2014-04-29 08:08
MOT test number	108999014195
Result	✓ Passed



MOT #2	2014-04-17 10:22
MOT test number	388387004106
Result	✗ Failed
Fail	Offside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #1	2013-03-26 09:05
MOT test number	895655983071
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
24 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	24 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SV10VLY
Plate since	2024-03-28
Current registration	 SV10VLY
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-26
Last registration	2023-07-25
Complete history	See info



Registration #1	2010-03-26	19 mi
Registration #2	2013-03-26	30.900 mi
Registration #3	2014-04-17	46.072 mi
Registration #4	2014-04-29	46.123 mi
Registration #5	2014-10-08	50.842 mi
Registration #6	2015-09-22	65.936 mi
Registration #7	2016-02-01	70.074 mi
Registration #8	2017-03-01	78.197 mi
Registration #9	2018-02-13	84.328 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2020-05-29	105.377 mi
Registration #12	2021-05-29	115.377 mi
Registration #13	2022-05-29	125.377 mi
Registration #14	2023-05-29	135.377 mi
Registration #15	2024-05-29	145.377 mi
Registration #16	2025-05-29	155.377 mi
Registration #17	2026-05-29	165.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1928 mm
Height	1726 mm
Length	4754 mm
Wheel base	2855 mm
Kerb weight	2321 kg
Max. allowed weight	2945 kg

Additional information

Fuel tank capacity	100 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CAS 098427