



report date: 2024-03-28

General information

Make	FORD
Model	GALAXY LX TDCI
Colour	Blue
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2022-01-21
Pictures	13
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #20	2022-01-18 12:27
MOT test number	360010613282
Result	✓ Passed
Next expiry date	2023-01-17
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Minor	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #19	2022-01-18 08:18
MOT test number	571747909205
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Fail	Offside Rear Seat belt not functioning as intended seat fitted wrong side (7.1.2 (c))
Minor	Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
Fail	Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Fail	Nearside Rear Seat belt not functioning as intended seat fitted wrong side (7.1.2 (c))
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
Minor	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #18**

2020-08-14 13:20

MOT test number

656800900174

Result

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #17

2019-10-02 11:51

MOT test number

815665253458

Result

✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #16**

2018-10-01 15:16

MOT test number

909403461460

Result

✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #15**

2018-10-01 11:00

MOT test number

513268959413

Result**✗ Failed**

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #14**

2017-09-19 08:43

MOT test number

364595063982

Result

✓ Passed

- Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)
- Advice** High brake light not working
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #13

2016-10-05 16:04

MOT test number

837252632369

Result

✓ Passed

- Advice** Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** High level brake light inop
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #12**

2016-09-29 14:21

MOT test number

329605014761

Result**✗ Failed****Advice** High level brake light inop**Fail** Nearside Rear Trailing arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Trailing arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11**

2015-12-04 18:49

MOT test number

912738025258

Result**✓ Passed****Advice** O/s rear tyre outer wall perishing**Advice** O/s front tyre outer wall perishing

**MOT #10** 2015-12-04 18:49**MOT test number** 768853952906**Result** ✗ Failed**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** O/s rear tyre outer wall perishing**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**Advice** O/s front tyre outer wall perishing**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**MOT #9** 2014-10-29 13:42**MOT test number** 786742404321**Result** ✓ Passed**MOT #8** 2013-11-07 18:27**MOT test number** 459131213449**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2013-11-07 12:09**MOT test number** 108731513322**Result** ✗ Failed**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6**

2012-11-02 11:46

MOT test number

748987402388

Result

✓ Passed

- Notice** Rear exhaust heatshield insecure
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Under-trays fitted obscuring some underside components

MOT #5

2012-11-02 11:46

MOT test number

209457202397

Result

✗ Failed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Notice** Under-trays fitted obscuring some underside components
- Pass with rectification** Offside Outer Rear position lamp(s) not working (1.1.A.3b)
- Notice** Rear exhaust heatshield insecure
- Pass with rectification** Offside Headlamp aim too high and too far to the left. (1.8)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Pass with rectification** Nearside Headlamp aim too high (1.8)

**MOT #4** 2012-10-31 11:32**MOT test number** 366435202362**Result** ✗ Failed

- Fail** Rear registration plate delaminated (6.3.1d)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Service brake: efficiency below requirements (3.7.B.7)

MOT #3 2011-11-10 11:04**MOT test number** 679924711338**Result** ✓ Passed**MOT #2** 2011-11-10 11:04**MOT test number** 439074211410**Result** ✗ Failed

- Pass with rectification** Rear Stop lamp not working (1.2.1b)

MOT #1 2010-11-04 11:42**MOT test number** 493558800413**Result** ✓ Passed



Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-09-30
Last registration	2022-01-18
Complete history	See info



Registration #1	2007-09-30	16 mi
Registration #2	2010-11-04	117.478 mi
Registration #3	2011-11-10	130.269 mi
Registration #4	2012-11-02	141.138 mi
Registration #5	2013-11-07	149.898 mi
Registration #6	2013-11-07	149.898 mi
Registration #7	2014-10-29	159.941 mi
Registration #8	2015-12-04	172.556 mi
Registration #9	2015-12-04	172.556 mi
Registration #10	2016-09-29	179.233 mi
Registration #11	2016-09-29	179.233 mi
Registration #12	2016-09-29	179.233 mi
Registration #13	2016-09-29	179.233 mi
Registration #14	2016-09-29	179.233 mi
Registration #15	2016-09-29	179.233 mi
Registration #16	2016-09-29	179.233 mi
Registration #17	2016-09-29	179.233 mi
Registration #18	2016-09-29	179.233 mi
Registration #19	2016-09-29	179.233 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1793 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

7K35212