





report date: 2024-03-29

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Black
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 3.250 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 2

Date 2022-01-30

Pictures 25

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2022-01-22	
-----------------	--

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT #15 2022-08-30 12:36

MOT test number 311880414295

Result ✓ Passed

Next expiry date 2023-08-31

MOT #14 2022-08-30 11:48

MOT test number 198023058752

Result X Failed

DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #13 2021-09-01 16:27

MOT test number 770557295117

Result \(\sqrt{Passed} \)

Advice Rear Trailing arm bushes worn

MOT #12 2021-04-16 08:52

MOT test number 731903770724

Result
✓ Passed

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

MOT #11 2020-05-04 08:50

MOT test number 793110336067

Result
✓ Passed

Advice Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm 'front bush' mountings corroding and debonding (5.3.4 (a) (i))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #10 2020-05-04 08:50

MOT test number 841316120307

Result X Failed

Advice Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm 'front bush' mountings corroding and debonding (5.3.4 (a) (i))

Pass with rectification

Offside Headlamp aim too high (4.1.2 (a))

MOT #9 2019-05-16 10:53

MOT test number 935129782163

Result ✓ Passed

MOT #8 2019-01-30 13:21

MOT test number 713514181045

Result ✓ Passed

MOT #7 2018-11-10 10:30

MOT test number 794386256796

Result \rightarrow Passed

Advice Under covers fitted.

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #6 2017-11-25 11:27

MOT test number 184283428264

Result \rightarrow Passed

Advice Under covers fitted.

MOT #5 2016-11-19 13:05

MOT test number 641094248871

Result

Passed

Advice Under covers fitted.

CarCheck.co.uk page 4/11



report date: 2024-03-29

MOT #4

MOT test number

959256839194

Result

Advice Under covers fitted.

Advice Engine covers fitted.

MOT #3 2014-11-26 14:26 **MOT** test number 458780934495 Result ✓ Passed **Notice** Vehicle's internal headlight adjuster altered to recheck lights Notice Child seat fitted not allowing full inspection of adult belt Notice Engine covers fitted obscuring some components in the engine bay **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) Notice Under-trays fitted obscuring some underside components

MOT #2

MOT test number

486352433446

Result

√ Passed

MOT test number

Result

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Notice Front wiper blades smearing

Notice Oil leak

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is		:?
THE STATE OF THE S		

	More info >	
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-09-30
Last registration	2022-08-30
Complete history	See info



Registration #1	2010-09-30	9 mi
Registration #2	2013-08-20	30.541 mi
Registration #3	2013-11-28	32.407 mi
Registration #4	2014-11-26	39.865 mi
Registration #5	2015-11-28	46.257 mi
Registration #6	2016-11-19	52.635 mi
Registration #7	2017-11-25	58.488 mi
Registration #8	2018-11-10	65.079 mi
Registration #9	2019-01-30	66.070 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 10/11



MA60DDV report date: 2024-03-29

Car features

S0225 S0295 Air conditioning

S0482

S0501

S0566

S0567

S0569

View the complete FORD factory list for this vehicle <u>here</u>.

The FORD factory car options list is only available in the premium report.

More info >

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles CarCheck.co.uk	2 page 11/11

Engine number

AU21080