



TOYOTA



report date: 2024-03-29

General information

| | |
|---------------------|---------------------|
| Make | TOYOTA |
| Model | CELICA T SPORT VVTI |
| Colour | Red |
| Year of manufacture | 2003 |
| Top speed | 140 mph |
| 0 - 60 mph | 7.2 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 189 BHP |
| Max. torque | 179 Nm at 6.800 rpm |
| Engine capacity | 1.796 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 24.6 mpg |
| Consumption extra urban | 42.8 mpg |
| Consumption combined | 33.6 mpg |
| CO2 emission | 200 g/km |
| CO2 label | J |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-12-04 |
| Pictures | 8 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2022-04-16 |
| MOT pass rate | 83 % |
| MOT passed | 15 |
| Failed MOT tests | 3 |
| Total advice items | 41 |
| Total items failed | 8 |

MOT #18 2023-01-19 08:09

MOT test number 677616611519

Result ✗ Failed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
- Fail** Offside Front Lower Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #17** 2021-04-17 10:26**MOT test number** 146691182387**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #16** 2021-03-15 11:17**MOT test number** 238602708378**Result** ✗ Failed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**MOT #15** 2020-03-02 13:39**MOT test number** 510758518916**Result** ✓ Passed**MOT #14** 2019-02-27 09:50**MOT test number** 405860489086**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #13** 2018-02-28 10:05**MOT test number** 616777178370**Result** ✓ Passed

**MOT #12**

2017-01-30 11:27

MOT test number

415758868017

Result

✓ Passed

- Advice** Nearside Rear tyre is bobbing on inner edge
- Advice** Vehicle structure has slight corrosion (6.1.B.2)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #11

2016-03-01 12:45

MOT test number

453796930486

Result

✓ Passed

- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #10

2015-05-12 14:56

MOT test number

466502935161

Result

✓ Passed

- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Nsf wheel bearing starting to wear
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Rear Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Nsf+osf+osr tyre inner edges starting to deform slightly
- Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)

**MOT #9**

2014-03-06 17:31

MOT test number

849125964042

Result

✓ Passed

- Notice** Plastic trim covering sills
- Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)
- Advice** Offside rear brake fluctuating, but not excessively (3.7.B.3)
- Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)
- Notice** Nsf tyre slight damage to inner wall
- Advice** Nearside rear brake fluctuating, but not excessively (3.7.B.3)

MOT #8

2014-03-05 12:04

MOT test number

195174964462

Result

✗ Failed

- Notice** Nsf tyre slight damage to inner wall
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Offside front brake fluctuating, but not excessively (3.7.B.3)
- Notice** Plastic trim covering sills
- Advice** Offside rear brake fluctuating, but not excessively (3.7.B.3)
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)
- Advice** Nearside rear brake fluctuating, but not excessively (3.7.B.3)

**MOT #7** 2012-11-30 16:43**MOT test number** 938205032343**Result** ✓ Passed**Notice** Front brake pipe corroded**Notice** Nsf wiper blade split**MOT #6** 2011-11-29 14:58**MOT test number** 918193731385**Result** ✓ Passed**MOT #5** 2010-03-17 10:21**MOT test number** 922996170076**Result** ✓ Passed**MOT #4** 2009-03-30 14:03**MOT test number** 860739089088**Result** ✓ Passed**MOT #3** 2008-05-14 15:21**MOT test number** 460625638105**Result** ✓ Passed**MOT #2** 2007-05-23 12:53**MOT test number** 222503147404**Result** ✓ Passed**MOT #1** 2006-06-01 15:58**MOT test number** 582952356113**Result** ✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

| | |
|----------|--|
| Damage 1 | |
| Date | |
| Category | |
| Type | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | YV03YPG |
| Plate since | 2019-03-29 |
| Current registration | YV03YPG |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 20 |
| First mileage registration | 2003-06-07 |
| Last registration | 2023-01-19 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2003-06-07 | 15 mi |
| Registration #2 | 2006-06-01 | 25.484 mi |
| Registration #3 | 2007-05-23 | 29.325 mi |
| Registration #4 | 2008-05-14 | 32.145 mi |
| Registration #5 | 2009-03-30 | 34.911 mi |
| Registration #6 | 2010-03-17 | 42.256 mi |
| Registration #7 | 2011-11-29 | 58.505 mi |
| Registration #8 | 2012-11-30 | 66.232 mi |
| Registration #9 | 2014-03-05 | 74.398 mi |
| Registration #10 | 2014-03-06 | 74.398 mi |
| Registration #11 | 2015-03-20 | 75.377 mi |
| Registration #12 | 2016-03-20 | 75.377 mi |
| Registration #13 | 2017-03-20 | 75.377 mi |
| Registration #14 | 2018-03-20 | 75.377 mi |
| Registration #15 | 2019-03-20 | 75.377 mi |
| Registration #16 | 2020-03-20 | 75.377 mi |
| Registration #17 | 2021-03-20 | 75.377 mi |
| Registration #18 | 2022-03-20 | 75.377 mi |
| Registration #19 | 2023-01-19 | 75.377 mi |
| Registration #20 | 2023-01-19 | 75.377 mi |

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|---------------------|---------|
| Width | 1735 mm |
| Height | 1315 mm |
| Length | 4350 mm |
| Wheel base | 2600 mm |
| Max. allowed weight | 1595 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 55 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of axles | 2 |
| Engine number | 2ZZ0115893 |