



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Blue
Year of manufacture	2005
Top speed	115 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	169 Nm at 2.400 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	40.4 mpg
Consumption combined	32.5 mpg
CO2 emission	209 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-08-29
Pictures	12
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-07-03
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	23
Total items failed	17

MOT #22	2022-06-14 17:24
MOT test number	939477873027
Result	✓ Passed
Next expiry date	2023-07-03
Advice	Nearside Rear Exhaust silencer slightly loose (8.1.1 (b) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear Passenger seat(s) missing at time of test all rears
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
Advice	Nearside Front Vehicle structure is corroded but structural rigidity is not significantly reduced outer cill (6.1.1 (c) (i))

MOT #21	2021-06-28 13:48
MOT test number	348582389521
Result	✓ Passed

**MOT #20** 2021-06-28 09:23**MOT test number** 272925342408**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #19** 2020-06-25 13:20**MOT test number** 215916793230**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #18** 2019-06-28 11:43**MOT test number** 879407341478**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #17** 2019-06-27 16:18**MOT test number** 310042378196**Result** ✗ Failed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #16** 2018-06-13 14:06**MOT test number** 514931459742**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #15** 2017-06-28 15:03**MOT test number** 317807639024**Result** ✓ Passed**MOT #14** 2017-06-27 09:43**MOT test number** 374015446596**Result** ✗ Failed**Advice** Offside Rear TYREWORN ON SIDEWALL**Fail** Tyre has a cut in excess of the requirements deep enough to reach the ply or cords BADLY CRACKED (4.1.D.1a)**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #13** 2016-07-04 08:33**MOT test number** 384798070736**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front INNER RACK END HAS SLIGHT PLAY

**MOT #12** 2016-06-29 10:52**MOT test number** 337427966342**Result** ✗ Failed**Advice** Offside Front INNER RACK END HAS SLIGHT PLAY**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #11** 2015-06-12 13:22**MOT test number** 108933765138**Result** ✓ Passed**MOT #10** 2014-10-03 11:01**MOT test number** 535956774214**Result** ✓ Passed**MOT #9** 2014-10-02 12:53**MOT test number** 435425974287**Result** ✗ Failed**Fail** Emissions not tested (7.3.A.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #8** 2013-09-30 10:23**MOT test number** 205483373245**Result** ✓ Passed**Notice** N/s/f indicator clear lens damaged**MOT #7** 2012-08-22 12:19**MOT test number** 818525532245**Result** ✓ Passed**MOT #6** 2011-08-27 14:45**MOT test number** 856949031250**Result** ✓ Passed**MOT #5** 2010-09-20 14:15**MOT test number** 982053160235**Result** ✓ Passed**Notice** Front brake discs pitted**MOT #4** 2010-09-20 14:15**MOT test number** 893123560212**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Notice** Front brake discs pitted**MOT #3** 2009-09-16 14:03**MOT test number** 740659159273**Result** ✓ Passed



MOT #2	2008-09-08 10:32
MOT test number	221412558293
Result	✓ Passed

MOT #1	2008-09-05 11:20
MOT test number	320499448423
Result	✗ Failed
Fail	Offside Rear Stop lamp not working (1.2.1b)
Fail	Offside Front Headlamp not in good working order adversely affecting beam image (1.2.4a)





Tax & MOT check

✕  
Untaxed

Tax expired:  
21 February 2023

✕  
MOT

Expired:  
3 July 2023

Tax status	Expired at 21 February 2023
Days left	434 days too late
MOT expiry date	3 July 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	YG55LYZ
Plate since	2024-03-29
Current registration	YG55LYZ
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-09-15
Last registration	2022-06-14
Complete history	<a href="#">See info</a>



Registration #1	2005-09-15	10 mi
Registration #2	2008-09-05	24.881 mi
Registration #3	2008-09-08	24.881 mi
Registration #4	2009-09-16	29.258 mi
Registration #5	2010-09-20	32.861 mi
Registration #6	2011-08-27	39.828 mi
Registration #7	2012-08-22	46.300 mi
Registration #8	2013-09-30	55.007 mi
Registration #9	2014-10-02	63.267 mi
Registration #10	2014-10-03	63.267 mi
Registration #11	2015-06-12	70.060 mi
Registration #12	2016-06-29	74.066 mi
Registration #13	2016-06-29	74.066 mi
Registration #14	2016-06-29	74.066 mi
Registration #15	2016-06-29	74.066 mi
Registration #16	2016-06-29	74.066 mi
Registration #17	2016-06-29	74.066 mi
Registration #18	2016-06-29	74.066 mi
Registration #19	2016-06-29	74.066 mi
Registration #20	2016-06-29	74.066 mi
Registration #21	2016-06-29	74.066 mi
Registration #22	2016-06-29	74.066 mi
Registration #23	2016-06-29	74.066 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1836 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Kerb weight	1309 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	AZJ 736618