





report date: 2024-03-29

General information

Make	BMW	
Model	640 640D M SPORT GRAN COUPE	
Colour	Black	
Year of manufacture	-	
Top speed	155 mph	
0 - 60 mph	5.4 seconds	
Gearbox	8 speed automatic	

Engine & fuel consumption

Power	308 BHP	
Max. torque	630 Nm at 1.500 rpm	
Cylinders	6	
Fuel type	Diesel	
Consumption city	40.9 mpg	
Consumption extra urban	57.7 mpg	
Consumption combined	49.6 mpg	



CarCheck.co.uk page 1/10



Internet history

Entry 3

Date 2024-02-26

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date 2021-12-18

Pictures 21

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2021-09-23

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



MOT history

MOT #9	2023-11-30 16:20
MOT test number	475373340116
Result	✓ Passed
Next expiry date	2024-11-29
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #8	2023-11-24 17:42
MOT test number	108178508969
Result	X Failed
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its s (5.2.3 (d) (ii))	structure outer sidewall

MOT #7	2022-11-17 13:08
MOT test number	485917506610
Result	✓ Passed
Advice Rear Tyre worn close to legal limit/worn on edge Both sides (5.2.3 (e))	

523579944701
✓ Passed

MOT #5	2021-03-01 16:34
MOT test number	327472971596
Result	✓ Passed

MOT #4	2020-02-21 08:55
MOT test number	859626032708
Result	✓ Passed
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 3/10



MOT #3 2019-03-09 09:46 **MOT test number** 636336538863 Result Passed **Advice** Engine covers and under trays obscuring some components Child Seat fitted not allowing full inspection of adult belt fitted to rear seat **Advice**

MOT #2 2018-03-09 14:16 **MOT** test number 396339297348 Result ✓ Passed

MOT #1 2018-03-08 11:05 333440000023 **MOT test number**

× Failed Result

Fail

Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NIX NIX
Flate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 7/10



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-03-20
Last registration	2023-11-30
Complete history	See info



Registration #1	2015-03-20	23 mi
Registration #2	2018-03-08	19.849 mi
Registration #3	2018-03-09	19.849 mi
Registration #4	2019-03-09	22.467 mi
Registration #5	2020-02-21	24.140 mi
Registration #6	2021-03-01	27.215 mi
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		0.00 44
Registration #13		70.777 au

More info >

CarCheck.co.uk page 9/10



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	78%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1894 mm
Height	1392 mm
Length	5007 mm
Wheel base	2968 mm
Kerb weight	1790 kg
Max. allowed weight	2410 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 page 1	10/10

Number of axles 2

Engine number 32089039