



report date: 2024-03-29

General information

Make	CITROEN
Model	C5 HDI VTR PLUS NAV
Colour	Black
Year of manufacture	2010
Top speed	160 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	160 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	147 g/km
CO2 label	F






Internet history

Entry 1

Date	2022-06-03
Pictures	8
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-14
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	29
Total items failed	1

MOT #14	2023-09-08 14:39
MOT test number	206332186362
Result	✓ Passed
Next expiry date	2024-09-14
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Osr and nsr shocks corroded slightly
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13**

2023-09-01 11:47

MOT test number

484169412379

Result

✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))
- MAJOR** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- MAJOR** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Osr and nsr shocks corroded slightly

MOT #12

2022-09-15 15:59

MOT test number

544931539386

Result

✓ Passed

MOT #11

2021-11-05 09:00

MOT test number

383527427302

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2020-11-19 16:26**MOT test number** 870721849554**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9** 2020-11-18 08:58**MOT test number** 488188355570**Result** ✗ Failed**DANGEROUS** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #8** 2019-05-10 08:01**MOT test number** 863394644357**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #7** 2018-05-10 08:59**MOT test number** 151538568822**Result** ✓ Passed**MOT #6** 2017-05-09 08:00**MOT test number** 806921995425**Result** ✓ Passed

**MOT #5** 2016-05-17 11:58**MOT test number** 448139818402**Result** ✓ Passed**MOT #4** 2015-05-18 15:28**MOT test number** 126888835104**Result** ✓ Passed**MOT #3** 2014-05-16 10:46**MOT test number** 509056334180**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2013-05-23 16:26**MOT test number** 887973143158**Result** ✓ Passed**MOT #1** 2013-05-20 16:03**MOT test number** 659030043149**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
14 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	14 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-04-19
Last registration	2023-09-08
Complete history	See info



Registration #1	2010-04-19	27 mi
Registration #2	2013-05-20	44.626 mi
Registration #3	2013-05-23	44.626 mi
Registration #4	2014-05-16	53.715 mi
Registration #5	2015-05-18	60.177 mi
Registration #6	2016-05-17	67.975 mi
Registration #7	2017-05-09	73.727 mi
Registration #8	2018-05-10	80.098 mi
Registration #9	2019-05-09	86.469 mi
Registration #10	2020-05-09	92.840 mi
Registration #11	2021-05-09	99.211 mi
Registration #12	2022-05-09	105.582 mi
Registration #13	2023-05-09	111.953 mi
Registration #14	2024-05-09	118.324 mi
Registration #15	2025-05-09	124.695 mi
Registration #16	2026-05-09	131.066 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	81%
Children	77%
Pedestrian	32%
Safety systems	83%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1860 mm
Height	1451 mm
Length	4779 mm
Wheel base	2815 mm
Kerb weight	1563 kg
Max. allowed weight	2156 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	DYWS4017889