



HYUNDAI



report date: 2024-03-28

General information

| | |
|---------------------|-------------------|
| Make | HYUNDAI |
| Model | AMICA CDX |
| Colour | Black |
| Year of manufacture | 2007 |
| Top speed | 86 mph |
| 0 - 60 mph | 18.9 seconds |
| Gearbox | 4 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|--------------------|
| Power | 62 BHP |
| Max. torque | 98 Nm at 3.000 rpm |
| Engine capacity | 1.086 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 35.3 mpg |
| Consumption extra urban | 56.5 mpg |
| Consumption combined | 46.3 mpg |
| CO2 emission | 145 g/km |
| CO2 label | F |







Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-09-28 |
| Pictures | 10 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-05 |
| MOT pass rate | 93 % |
| MOT passed | 14 |
| Failed MOT tests | 1 |
| Total advice items | 9 |
| Total items failed | 4 |

| | |
|------------------|---|
| MOT #15 | 2023-10-06 08:40 |
| MOT test number | 963548960800 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-05 |
| Advice | Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c)) |

| | |
|-----------------|---|
| MOT #14 | 2023-10-03 09:12 |
| MOT test number | 582300516055 |
| Result | ✗ Failed |
| Fail | Nearside Rear Tyre has ply or cords exposed Tyre cracking on tread (5.2.3 (d) (ii)) |
| Advice | Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c)) |
| Fail | Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii)) |
| Fail | Offside Rear Tyre has ply or cords exposed Tyre cracking on tread cords exposed (5.2.3 (d) (ii)) |
| Fail | Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |

| | |
|-----------------|------------------|
| MOT #13 | 2022-10-04 15:41 |
| MOT test number | 766951302643 |
| Result | ✓ Passed |

**MOT #12** 2021-09-10 14:03**MOT test number** 529068326511**Result** ✓ Passed**MOT #11** 2020-11-20 14:51**MOT test number** 529009666287**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2019-08-17 08:37**MOT test number** 826205400957**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2018-08-17 11:57**MOT test number** 560074308878**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2017-08-05 07:46**MOT test number** 461692905314**Result** ✓ Passed**MOT #7** 2016-08-19 14:58**MOT test number** 675153617724**Result** ✓ Passed



| | |
|---------------|------------------|
| MOT #6 | 2015-08-20 14:54 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 885772935282 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #5 | 2014-08-22 09:07 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 365824034485 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #4 | 2013-08-14 12:34 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 388696623245 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #3 | 2012-07-25 14:39 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 408037502203 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #2 | 2011-08-03 10:33 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 426465011225 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #1 | 2010-07-29 09:32 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 760650710268 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
5 October 2024

| | | |
|------------------|--|---------------------------------|
| Tax status | | Valid until 1 October |
| Days left | | 156 |
| MOT expiry date | | 5 October 2024 |
| Full MOT history | | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 48 |
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

| | |
|----------------------|---------------|
| Number of plates | 1 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |
| Current registration | XXXXXX |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 17 |
| First mileage registration | 2007-08-06 |
| Last registration | 2023-10-06 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2007-08-06 | 9 mi |
| Registration #2 | 2010-07-29 | 5.440 mi |
| Registration #3 | 2011-08-03 | 7.107 mi |
| Registration #4 | 2012-07-25 | 8.642 mi |
| Registration #5 | 2013-08-14 | 10.095 mi |
| Registration #6 | 2014-08-22 | 11.588 mi |
| Registration #7 | 2015-08-20 | 13.124 mi |
| Registration #8 | 2016-08-19 | 14.579 mi |
| Registration #9 | 2017-08-05 | 15.655 mi |
| Registration #10 | 2018-08-05 | 16.731 mi |
| Registration #11 | 2019-08-05 | 17.807 mi |
| Registration #12 | 2020-08-05 | 18.883 mi |
| Registration #13 | 2021-08-05 | 19.959 mi |
| Registration #14 | 2022-08-05 | 21.035 mi |
| Registration #15 | 2023-08-05 | 22.111 mi |
| Registration #16 | 2024-03-28 | 23.187 mi |
| Registration #17 | 2024-03-28 | 24.263 mi |

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|-------------|---------|
| Width | 1525 mm |
| Height | 1570 mm |
| Length | 3565 mm |
| Wheel base | 2380 mm |
| Kerb weight | 946 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 35 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 4 |
| Engine number | G4HG6M028672 |