



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTi
Colour	White
Year of manufacture	2016
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-02-05
Pictures	10
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-12-09
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	16
Total items failed	6

MOT #7	2023-12-05 12:01
MOT test number	730734245144
Result	✓ Passed
Next expiry date	2024-12-09
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #6**

2023-12-05 06:46

MOT test number

479296889147

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #5

2022-11-15 16:00

MOT test number

745792446457

Result**✓ Passed****MOT #4**

2022-11-15 16:00

MOT test number

482613960146

Result**✗ Failed**

- Pass with rectification** Nearside Rear Direction indicator not working (4.4.1 (a) (ii))

**MOT #3** 2021-12-10 10:36**MOT test number** 389332059318**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2020-12-03 14:37**MOT test number** 425036310361**Result** ✓ Passed**Advice** Nearside Front Nail in tyre**MOT #1** 2019-11-16 10:24**MOT test number** 265305815263**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
9 December 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	9 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-12-09
Last registration	2023-12-05
Complete history	See info



Registration #1	2016-12-09	12 mi
Registration #2	2019-11-16	40.014 mi
Registration #3	2020-12-03	48.211 mi
Registration #4		
Registration #5	2021-12-10	60.842 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		

More info >



Dimensions & weight

Width	2119 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1270 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A2000-5824911