



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	GL GL320 CDI
Colour	Black
Year of manufacture	2009
Top speed	130 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 2.800 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	22.6 mpg
Consumption extra urban	35.3 mpg
Consumption combined	28.8 mpg
CO2 emission	264 g/km
CO2 label	M






Internet history

Entry 1

Date	2021-09-28
Pictures	6
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-04
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	43
Total items failed	15

MOT #19 2024-02-05 10:26

MOT test number 276079208191

Result ✔ Passed

Next expiry date 2025-02-04

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #18 2024-01-16 15:22

MOT test number 273809967416

Result ✘ Failed

Advice Nsr disc pitted

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Central Rear Seat belt retracting mechanism defective (7.1.2 (e))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))



MOT #17 2023-01-13 15:41

MOT test number 330267817148

Result ✓ Passed

- Advice** Tow ball hitch not fitted at time of test!
- Advice** Tow bar electrical socket corroded!

MOT #16 2023-01-13 15:41

MOT test number 844384222528

Result ✗ Failed

- Advice** Tow ball hitch not fitted at time of test!
- Pass with rectification** Central Seat belt missing buckle missing (7.1.2 (a))
- Advice** Tow bar electrical socket corroded!
- Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #15 2022-05-04 15:18

MOT test number 724076294432

Result ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14 2022-04-29 12:54

MOT test number 618284668353

Result ✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Front Side repeater not working in mirror (4.4.1 (a) (ii))

MOT #13 2021-10-18 12:32

MOT test number 895929110644

Result ✓ Passed



MOT #12	2021-03-31 08:41
MOT test number	793991177698
Result	✓ Passed
Advice	Brake pad warning light on but pads are ok
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Passenger seat(s) missing at time of test 3rd row
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #11	2021-03-18 16:12
MOT test number	515215273557
Result	✗ Failed
Fail	Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Nail in tyre
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Nearside Rear Passenger's seat backrest cannot be secured in the upright position. 3rd row (6.2.6 (a) (i))
Advice	Brake pad warning light on but pads are ok
Fail	Nearside Front Brake hose damaged and likely to fail (1.1.12 (a))
Minor	Windscreen wiper blade defective Both smearing the screen (3.4 (b) (i))
Fail	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
Fail	Offside Front Brake hose damaged and likely to fail (1.1.12 (a))

MOT #10	2020-03-16 18:11
MOT test number	131894944557
Result	✓ Passed



MOT #9 2019-06-24 15:46

MOT test number 380208942477

Result ✔ Passed

Advice Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2018-01-18 14:44

MOT test number 657602218544

Result ✔ Passed

Advice Oil leak

MOT #7 2016-02-19 10:20

MOT test number 964213831982

Result ✔ Passed

Advice Nearside Rear Inner tyre close to the cords.

Advice Power steering pump noisy

Advice Offside Rear Inner tyre close to the cords.



MOT #6 2016-02-16 10:26

MOT test number 812553082910

Result ✗ Failed

Fail Front Lower Fuel system component leaking (7.2.3)

Advice Offside Rear Inner tyre close to the cords.

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Advice Nearside Rear Inner tyre close to the cords.

Advice Power steering pump noisy

Fail Nearside Headlamp not working on dipped beam (1.7.5a)

MOT #5 2014-12-31 10:11

MOT test number 958745864398

Result ✓ Passed

MOT #4 2014-01-21 09:49

MOT test number 428151324019

Result ✓ Passed

Notice Nail in offside rear tyre

MOT #3 2013-01-11 10:41

MOT test number 898511013077

Result ✓ Passed

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components



MOT #2 2013-01-10 11:08

MOT test number 986330413065

Result ✗ Failed

- Notice** Nail in nearside rear tyre
- Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
- Notice** Under-trays fitted obscuring some underside components
- Fail** Brake pedal anti-slip provision worn smooth (3.3.A.1b)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Nail in offside rear tyre
- Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #1 2012-01-05 13:24

MOT test number 548895702062

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✓
MOT

Expires:
4 February 2025

Tax status Valid until 1 October

Days left 155

MOT expiry date 4 February 2025

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	LC58DYY
Plate since	2019-03-29
Current registration	LC58DYY
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-01-30
Last registration	2024-02-05
Complete history	See info



Registration #1	2009-01-30	21 mi
Registration #2	2012-01-05	20.733 mi
Registration #3	2013-01-10	24.471 mi
Registration #4	2013-01-11	24.471 mi
Registration #5	2014-01-21	26.262 mi
Registration #6	2014-12-31	27.417 mi
Registration #7	2016-02-16	42.748 mi
Registration #8	2016-02-19	42.755 mi
Registration #9	2018-01-18	60.471 mi
Registration #10	2019-06-24	71.311 mi
Registration #11	2020-03-16	76.020 mi
Registration #12	2020-03-16	76.020 mi
Registration #13	2020-03-16	76.020 mi
Registration #14	2020-03-16	76.020 mi
Registration #15	2020-03-16	76.020 mi
Registration #16	2020-03-16	76.020 mi
Registration #17	2020-03-16	76.020 mi
Registration #18	2020-03-16	76.020 mi
Registration #19	2020-03-16	76.020 mi
Registration #20	2020-03-16	76.020 mi
Registration #21	2020-03-16	76.020 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	2127 mm
Height	1920 mm
Length	5088 mm
Kerb weight	2505 kg
Max. allowed weight	3250 kg

Additional information

Fuel tank capacity	100 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	64294040745255