





report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK SLK 200 KOMPRESSOR
Colour	Silver
Year of manufacture	2009
Top speed	155 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.9 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.5 mpg
CO2 emission	196 g/km
CO2 label	J



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-10-30

Pictures 42

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MO	T hi	istory	,
----	------	--------	---

MOT expiry date	2024-04-27
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	9
Total items failed	6

MOT #14	2023-04-24 15:02
MOT test number	690297455177
Result	✓ Passed
Next expiry date	2024-04-27

MOT #13	2022-04-22 13:50
MOT test number	999184505901
Result	✓ Passed

MOT #12	2021-04-28 09:53
MOT test number	740844798849
Result	✓ Passed

Advice Offside Front Outer Integral body structure is deformed but structural rigidity is not significantly reduced sill outer cover (6.1.1 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

900100315430

Result

Advice Offside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Front Outer Integral body structure is deformed but structural rigidity is not significantly reduced sill outer cover (6.1.1 (a) (i))

Pass with rectification Nearside Front Windscreen wiper not working (3.4 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MOT #10	2020-02-10 15:36
MOT test number	924896682046
Result	✓ Passed
MOT #9	2018-06-11 10:18
MOT test number	626721317461
Result	✓ Passed
MOT #8	2017-06-16 08:06
MOT test number	654881430773
Result	✓ Passed
MOT #7	2017-06-15 10:04
MOT test number	946340002220
Result	× Failed
Fail Offside Front coil spring broken (2.4.C.1a)	

MOT #6	2016-06-13 09:38
MOT test number	363044941642
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5

MOT test number

Result

Notice Under-trays fitted obscuring some underside components

Notice Engine covers fitted obscuring some components in the engine bay

MOT #4

MOT test number

Result

MOT #3

MOT test number

2014-05-30 14:36

428390154161

✓ Passed

MOT #3

429159113146

Result \rightarrow Passed

MOT #2 2013-04-26 14:18

MOT test number 737876013185

Result X Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #1 2012-05-23 11:18
MOT test number 788324542182

Result ✓ Passed

Advice Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

CarCheck.co.uk page 5/12



X

report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	27 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	

Damage 2

Damage 2	
Date	
Category	

Type



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.	

Diate changes	More info >
Plate changes See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	UK SIP
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-05-26
Last registration	2023-04-24
Complete history	See info



Registration #1	2009-05-26	10 mi
Registration #2	2012-05-23	21.118 mi
Registration #3	2013-04-26	25.934 mi
Registration #4	2013-04-29	25.934 mi
Registration #5	2014-05-30	30.109 mi
Registration #6	2015-06-04	32.968 mi
Registration #7	2016-06-13	35.715 mi
Registration #8	2017-06-15	38.031 mi
Registration #9		11.177 es
Registration #10		11.777 es
Registration #11		91.077 mi
Registration #12		11.177 es
Registration #13		91.077 mi
Registration #14		11.177 es
Registration #15		11.777 mg
Registration #16		10.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

		_		
- 11	manciai	חר ג.	MOIG	nt.
	mensioı	אט כוו	welu	III.

Width	2012 mm
Height	1296 mm
Length	4103 mm
Wheel base	2430 mm
Kerb weight	1415 kg
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27195431253706

CarCheck.co.uk page 12/12