



report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO 2000 L1H1 CDTI S/S ECOFLEX
Colour	White
Year of manufacture	2015
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	126 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-07-18
Pictures	18
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2024-05-17
<b>MOT pass rate</b>	67 %
<b>MOT passed</b>	6
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	31
<b>Total items failed</b>	5

**MOT #9** 2023-05-18 10:15**MOT test number** 913533291950**Result** Passed**Next expiry date** 2024-05-17

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2022-06-20 07:42**MOT test number** 516355905379**Result** Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing was made week 40 of year 2014 (5.2.3 (d) (ii))
- Advice** Nearside Rear is a winter tyre
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge bald so unable to determine the tyre life (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #7** 2021-07-12 14:42**MOT test number** 125491822439**Result** Passed

**MOT #6** 2020-10-28 10:39**MOT test number** 114299579139**Result** ✓ Passed**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil light is on**MOT #5** 2020-10-26 13:43**MOT test number** 627967132830**Result** ✗ Failed**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))**Advice** Oil light is on**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2019-04-01 15:43**MOT test number** 274289938181**Result** ✓ Passed**Advice** Nail in tyre staple in tyre**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Protective shield fitted underneath vehicle / preventing full inspection

**MOT #3** 2019-04-01 10:38**MOT test number** 871321771700**Result** ✗ Failed**Advice** Clutch pedal rubber missing**Fail** Brake pedal anti-slip provision missing (1.1.2 (c))**Advice** Nail in tyre staple in tyre**Advice** Protective shield fitted underneath vehicle / preventing full inspection**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #2** 2018-04-16 07:15**MOT test number** 419553551228**Result** ✓ Passed**Advice** Nearside front tyre worn on outer edge**Advice** Tyre size: 185/65 R15 92T**Advice** Undercover tray fitted to vehicle



MOT #1

2018-04-10 11:45

MOT test number

637279338512

Result

✗ Failed

- Advice

Engine management light illuminated
- Advice

Blue smoke coming from exhaust when emissions carried out
- Advice

Nearside front tyre worn on outer edge
- Fail

Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure outer sidewall (4.1.D.1b)
- Advice

Tyre size: 185/65 R15 92T
- Advice

Warning light illuminated on dash
- Advice

Parking brake requires adjustment
- Fail

Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure outer and inner sidewall (4.1.D.1b)
- Advice

Undercover tray fitted to vehicle
- Fail

Trailer electrical socket damaged so that lead cannot be securely connected 7 pin (1.9.3b)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2024

✓  
**MOT**  
**Expires:**  
17 May 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	3
<b>MOT expiry date</b>	17 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>XX15LNO</b>
Plate since	2019-03-28
Current registration	 <b>XX15LNO</b>
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-04-28
Last registration	2023-05-18
Complete history	<a href="#">See info</a>



Registration #1	2015-04-28	18 mi
Registration #2	2018-04-10	9.277 mi
Registration #3	2018-04-16	9.279 mi
Registration #4	2019-04-01	12.279 mi
Registration #5	2019-04-01	12.279 mi
Registration #6	2020-10-26	56.637 mi
Registration #7	2023-05-18	56.637 mi
Registration #8	2023-05-18	56.637 mi
Registration #9	2023-05-18	56.637 mi
Registration #10	2023-05-18	56.637 mi
Registration #11	2023-05-18	56.637 mi

More info >



Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	263A20005564913 LN9