



RENAULT

SM60PHJ

report date: 2024-03-28

General information

Make	RENAULT
Model	GRAND SCENIC DYNAMIQUE TOMTOM BOSE PACK DCI
Colour	Grey
Year of manufacture	2011
Top speed	112 mph
0 - 100 km/h	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	78 kW / 106 HP / 110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	128 g/km
CO2 label	D






## Internet history

### Entry 2

Date	2022-02-03
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)

### Entry 1

Date	2021-02-04
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://autoonline.co.uk)



## MOT history

MOT expiry date	2024-12-20
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	31
Total items failed	3

## MOT #14 2023-12-21 14:20

MOT test number 153054423856

Result ✓ Passed

Next expiry date 2024-12-20

**Minor** Nearside Front Lower Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

## MOT #13 2023-12-14 11:15

MOT test number 690509468166

Result ✗ Failed**MAJOR** Offside Front Headlamp aim too low (4.1.2 (a))**DANGEROUS** Offside Front Outer Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated Clip loose (6.1.7 (g) (i))**Advice** Nearside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Front Lower Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #12**

2022-12-07 17:09

**MOT test number**

266948589168

**Result**

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #11**

2022-12-07 11:56

**MOT test number**

911301115820

**Result**

✗ Failed

- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #10**

2021-12-10 15:08

**MOT test number**

488544041846

**Result**

✓ Passed

- Advice** Front tyres x 2 edges worn
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened x 2 (1.1.14 (a) (ii))

**MOT #9** 2019-10-12 11:14**MOT test number** 409499310876**Result** ✓ Passed**MOT #8** 2018-10-20 12:20**MOT test number** 352875332242**Result** ✓ Passed**MOT #7** 2018-10-20 11:21**MOT test number** 603167336117**Result** ✗ Failed**DANGEROUS** Front Tyre tread depth below requirements of 1.6mm both 205/60/16 (5.2.3 (e))**Advice** Tracking may need attention**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**DANGEROUS** Rear Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))**MOT #6** 2017-10-07 09:50**MOT test number** 670309660405**Result** ✓ Passed**MOT #5** 2016-10-25 08:27**MOT test number** 223458896256**Result** ✓ Passed

**MOT #4** 2016-10-15 11:20**MOT test number** 165971346590**Result** ✗ Failed**Fail** Offside Rear Direction indicator not working (1.4.A.2c)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #3** 2015-10-16 16:08**MOT test number** 622743167411**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-10-23 10:19**MOT test number** 345226094474**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2013-12-12 12:54**MOT test number** 576116543383**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
20 December 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	34
<b>MOT expiry date</b>	20 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-01-31
Last registration	2023-12-21
Complete history	<a href="#">See info</a>



Registration #1	2011-01-31	12 mi
Registration #2	2013-12-12	30.251 mi
Registration #3	2014-10-23	36.043 mi
Registration #4	2015-10-16	48.250 mi
Registration #5	2016-10-15	60.296 mi
Registration #6	2016-10-25	60.645 mi
Registration #7	2017-10-07	74.145 mi
Registration #8	2018-10-20	90.206 mi
Registration #9	2018-10-20	90.206 mi
Registration #10	2019-10-20	90.206 mi
Registration #11	2019-10-20	90.206 mi
Registration #12	2019-10-20	90.206 mi
Registration #13	2019-10-20	90.206 mi
Registration #14	2019-10-20	90.206 mi
Registration #15	2019-10-20	90.206 mi
Registration #16	2019-10-20	90.206 mi
Registration #17	2019-10-20	90.206 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1486 mm
Height	1637 mm
Length	4344 mm
Wheel base	2703 mm
Kerb weight	1385 kg
Max. allowed weight	1944 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D246598