



report date: 2024-03-29

General information

Make	NISSAN
Model	ALMERA S
Colour	Black
Year of manufacture	2003
Top speed	108 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	128 Nm at 2.800 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-05-25
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-15
MOT pass rate	83 %
MOT passed	19
Failed MOT tests	4
Total advice items	35
Total items failed	5

MOT #23	2023-05-23 12:52
MOT test number	194450341627
Result	✓ Passed
Next expiry date	2024-06-15
Minor	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #22	2022-06-16 11:19
MOT test number	567296198207
Result	✓ Passed
Minor	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Rear tyres wearing on the edge
Minor	Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #21	2021-05-28 12:46
MOT test number	573507785731
Result	✓ Passed

**MOT #20** 2021-05-26 11:45**MOT test number** 186675514153**Result** ✗ Failed

Fail Nearside Front Suspension component mounting prescribed area is corroded to the extent that control of the vehicle is likely to be adversely affected cross member radiator support (5.3.6 (a) (ii))

Fail Offside Front Suspension component mounting prescribed area is corroded to the extent that control of the vehicle is likely to be adversely affected cross member radiator support (5.3.6 (a) (ii))

MOT #19 2020-09-02 10:24**MOT test number** 336945569934**Result** ✓ Passed

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #18 2019-08-12 09:37**MOT test number** 481933014203**Result** ✓ Passed**MOT #17** 2018-09-10 10:55**MOT test number** 724679945144**Result** ✓ Passed

Advice Handbrake has little reserve travel

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Front cross member corroded

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2018-09-10 10:55

MOT test number

801372974689

Result**✗ Failed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Front cross member corroded**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Handbrake has little reserve travel**MOT #15**

2017-09-07 09:14

MOT test number

453743919999

Result**✓ Passed****Advice** Front Lower Subframe mounting prescribed area is corroded but not considered excessive radiator support panel (2.4.A.3)**MOT #14**

2016-09-06 10:21

MOT test number

355898493101

Result**✓ Passed****Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #13**

2015-09-04 09:01

MOT test number

317471045989

Result**✓ Passed**

**MOT #12** 2014-09-08 10:21**MOT test number** 989701354284**Result** ✓ Passed**Notice** N/S/R tyre tread breaking up**Notice** N/S/R seat belt not checked - child seat fitted**MOT #11** 2013-09-03 10:01**MOT test number** 189596043281**Result** ✓ Passed**MOT #10** 2012-08-15 09:56**MOT test number** 889378922220**Result** ✓ Passed**Notice** Rear number plate is starting to deteriorate**Notice** N/s/f tyre has 2.5mm tread**Notice** Front cross member corroding**MOT #9** 2012-08-15 09:56**MOT test number** 486718022213**Result** ✗ Failed**Notice** Front cross member corroding**Notice** Rear number plate is starting to deteriorate**Notice** N/s/f tyre has 2.5mm tread**Pass with rectification** Front Headlamp aim too low (1.8)

**MOT #8** 2011-09-01 11:50**MOT test number** 576594541242**Result** ✓ Passed**Notice** Misting of oil on power steering rack pump area**Notice** Front cross member corroding**Notice** N/s/f tyre wear on edge (tracking requires checking)**MOT #7** 2011-08-31 10:28**MOT test number** 688473741215**Result** ✗ Failed**Notice** Front cross member corroding**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Notice** N/s/f tyre wear on edge (tracking requires checking)**Notice** Misting of oil on power steering rack pump area**MOT #6** 2010-08-27 14:45**MOT test number** 302319830483**Result** ✓ Passed**Notice** Front cross member corroding**MOT #5** 2009-09-10 16:09**MOT test number** 982193459257**Result** ✓ Passed**MOT #4** 2009-03-18 12:59**MOT test number** 752107279020**Result** ✓ Passed



MOT #3	2008-03-27 11:42
MOT test number	773207588014
Result	✓ Passed

MOT #2	2007-03-29 11:47
MOT test number	720888587070
Result	✓ Passed
<div>Notice Front tyres worn on inside edges</div>	

MOT #1	2006-03-28 10:38
MOT test number	190337686485
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
15 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	15 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	PK03UPX
Plate since	2019-03-29
Current registration	PK03UPX
Plate since	2019-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-03-31
Last registration	2023-05-23
Complete history	See info



Registration #1	2003-03-31	8 mi
Registration #2	2006-03-28	10.505 mi
Registration #3	2007-03-29	14.167 mi
Registration #4	2008-03-27	17.808 mi
Registration #5	2009-03-18	21.594 mi
Registration #6	2009-09-10	23.202 mi
Registration #7	2010-08-27	34.016 mi
Registration #8	2011-08-31	43.455 mi
Registration #9	2011-09-01	43.455 mi
Registration #10	2012-08-15	51.915 mi
Registration #11	2013-09-03	60.546 mi
Registration #12	2014-09-08	64.384 mi
Registration #13	2015-05-20	75.377 mi
Registration #14	2016-05-20	75.377 mi
Registration #15	2017-05-20	75.377 mi
Registration #16	2018-05-20	75.377 mi
Registration #17	2019-05-20	75.377 mi
Registration #18	2020-05-20	75.377 mi
Registration #19	2021-05-20	75.377 mi
Registration #20	2022-05-20	75.377 mi
Registration #21	2023-05-20	75.377 mi
Registration #22	2024-05-20	75.377 mi
Registration #23	2025-05-20	75.377 mi
Registration #24	2026-05-20	75.377 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1170 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	197826