





General information

Make	ΤΟΥΟΤΑ
Model	VERSO VALVEMATIC T SPIRIT
Colour	Black
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	10.4 seconds
Gearbox	7 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	180 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	164 g/km
CO2 label	G







Internet history

Entry 1

Date

Pictures

Listing price

2021-02-05

4

View report









source: autoonline.co.uk



MOT history

MOT expiry date	2024-06-07
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	15
Total items failed	10

MOT #14	2023-06-08 10:28
MOT test number	167743079259
Result	✓ Passed
Next expiry date	2024-06-07

MOT #13	2021-12-02 14:56
MOT test number	842348151736
Result	✓ Passed
Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12		2020-12-14 18:31
MOT test	number	989890343915
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #11	2020-12-07 16:10
MOT test number	123697911045
Result	🗙 Failed
Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10	2019-11-29 11:06
MOT test number	293684408347
Result	✓ Passed

MOT #9	2019-11-29 11:06
MOT test number	686133815876
Result	× Failed
Pass with rectification	Front Registration plate does not conform to the specified requirements (0.1 (d))
Pass with rectification	Front Headlamp aim too high both (4.1.2 (a))

MOT #8	2018-01-18 09:57
MOT test number	981793415560
Result	✓ Passed

MOT #7		2016-12-22 12:58
MOT test	number	391133678388
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	





МОТ #6	2016-12-20 16:48
MOT test number	699729544586
Result	🗙 Failed
Fail Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Offside Headlamp not working on main beam (1.7.5a)	
Fail Offside Obligatory mirror seriously obscured affecting the rear view (8.1.2a)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2015-11-20 10:17
MOT test number	680799710531
Result	✓ Passed
AdviceNearside Rear Tyre worn close to the legal limit (4.1.E.1)AdviceOffside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2014-11-27 11:47
MOT test number	469301934456
Result	✓ Passed

MOT #3	2014-11-26 09:56
MOT test number	127030034332
Result	🗙 Failed
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	





MOT #2	2013-11-27 17:39
MOT test number	327221133334
Result	✓ Passed
MOT #1	2013-11-27 09:30
MOT test number	518371933347
Result	🗙 Failed
Fail Nearside Headlamp not working on dipped beam (1.7.5a)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✓ Taxed Tax due: 1 December 2024	✓ MOT Expires: 7 June 2024
Tax status	Valid until 1 December
Days left	216
MOT expiry date	7 June 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class48BandGSingle payment (12 months)£ 240,00,-Single six month payment£ 132,00,-Total payable by 12 monthly instalments£ 252,00,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	K K
Damage 2	AMPL
Date	NE
Category	AMP
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6 10.200
Auction value	4 10.202
Average private trade value	4 10.000





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-12-11
Last registration	2023-06-08
Complete history	See info



Registration #1	2009-12-11	6 mi
Registration #2	2013-11-27	36.392 mi
Registration #3	2013-11-27	36.392 mi
Registration #4	2014-11-26	45.748 mi
Registration #5	2014-11-27	45.748 mi
Registration #6	2015-11-20	53.777 mi
Registration #7	2016-12-20	63.008 mi
Registration #8	2016-12-22	63.048 mi
	2010 12 22	
Registration #9	1010 11 11 mm. m	11.777 esi
-	1010 11 11 1010 11 11 1010 10 10	11.227 est
Registration #9		01.000 est 01.000 est 01.000 est
Registration #9 Registration #10		00.000 est 0.000 est 00.000 est 00.000 est
Registration #9 Registration #10 Registration #11		01.000 est 01.000 est 01.000 est 01.000 est 01.000 est
Registration #9 Registration #10 Registration #11 Registration #12		00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est
Registration #9 Registration #10 Registration #11 Registration #12 Registration #13		00.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est 0.000 est





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
50566	
\$0567	
S0569	

Safety ratings

Number of axles

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1790 mm
Height	1630 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1525 kg
Max. allowed weight	2125 kg
Additional information	
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

2