



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	GETZ GSI
Colour	Silver
Year of manufacture	2003
Top speed	93 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	62 BHP
Max. torque	94 Nm at 3.200 rpm
Engine capacity	1.086 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-10-31
Pictures	16
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-07-07
MOT pass rate	86 %
MOT passed	18
Failed MOT tests	3
Total advice items	29
Total items failed	4

MOT #21 2023-07-04 11:00**MOT test number** 455307002413**Result** Passed**Next expiry date** 2024-07-07

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front headlamp bracket slightly damaged
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #20 2022-07-08 13:06**MOT test number** 210367387009**Result** Passed

- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #19** 2021-06-14 11:53**MOT test number** 147928073807**Result** ✓ Passed**Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #18** 2020-06-16 16:05**MOT test number** 924455229046**Result** ✓ Passed**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Hydraulic leak, but not excessive (8.4.1 (a) (i))**MOT #17** 2020-06-16 11:55**MOT test number** 312279423755**Result** ✗ Failed**MAJOR** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MAJOR** Power steering malfunctioning (2.1.5 (a))**MAJOR** Nearside Headlamp aim too low (4.1.2 (a))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Hydraulic leak, but not excessive (8.4.1 (a) (i))**MOT #16** 2019-06-17 11:12**MOT test number** 968553661269**Result** ✓ Passed**MOT #15** 2018-06-05 08:28**MOT test number** 950926445853**Result** ✓ Passed



MOT #14	2017-06-15 11:59
----------------	------------------

MOT test number	553571791933
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #13	2016-06-16 12:56
----------------	------------------

MOT test number	673801630011
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #12	2015-06-17 15:33
----------------	------------------

MOT test number	528708665182
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #11	2014-06-18 11:21
----------------	------------------

MOT test number	598869464139
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #10	2013-06-13 10:53
----------------	------------------

MOT test number	716074463112
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Advise o/s/f wheel bearing slightly rough when rotated
---------------	--

MOT #9	2012-06-15 09:32
---------------	------------------

MOT test number	346737062127
------------------------	--------------

Result	✓ Passed
---------------	----------

**MOT #8** 2011-06-14 11:12**MOT test number** 959205961176**Result** ✓ Passed

- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Shock absorber has a slightly reduced damping effect (2.7.5)
- Advice** Nearside Front Shock absorber has a slightly reduced damping effect (2.7.5)

MOT #7 2010-06-17 12:09**MOT test number** 554628860101**Result** ✓ Passed

- Advice** Nearside Front Shock absorber has a slightly reduced damping effect (2.7.5)
- Advice** Offside Front Shock absorber has a slightly reduced damping effect (2.7.5)

MOT #6 2009-06-15 15:32**MOT test number** 783906869105**Result** ✓ Passed**MOT #5** 2009-06-15 12:00**MOT test number** 863036269113**Result** ✗ Failed

- Fail** Offside Inner Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2008-06-17 08:59**MOT test number** 894129168125**Result** ✓ Passed

**MOT #3** 2008-06-11 11:24**MOT test number** 952253768117**Result** ✗ Failed**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Fail** Rear fog lamp tell tale not working (1.3.1b)**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #2** 2007-06-11 10:50**MOT test number** 453352467188**Result** ✓ Passed**Notice** Engine leaking oil**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2006-06-19 15:58**MOT test number** 453020676179**Result** ✓ Passed**Notice** Rear number plate fading & slightly loose.



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
7 July 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	7 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EY03KVS
Plate since	2019-03-28
Current registration	EY03KVS
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2003-06-23
Last registration	2023-07-04
Complete history	See info



Registration #1	2003-06-23	13 mi
Registration #2	2006-06-19	17.068 mi
Registration #3	2007-06-11	21.714 mi
Registration #4	2008-06-11	23.595 mi
Registration #5	2008-06-17	23.631 mi
Registration #6	2009-06-15	26.924 mi
Registration #7	2009-06-15	26.924 mi
Registration #8	2010-06-17	30.642 mi
Registration #9	2011-06-14	33.959 mi
Registration #10	2012-06-15	37.066 mi
Registration #11	2013-06-13	40.321 mi
Registration #12	2014-06-18	42.431 mi
Registration #13	2015-06-20	45.542 mi
Registration #14	2016-06-22	48.653 mi
Registration #15	2017-06-24	51.764 mi
Registration #16	2018-06-26	54.875 mi
Registration #17	2019-06-28	57.986 mi
Registration #18	2020-06-30	61.097 mi
Registration #19	2021-07-02	64.208 mi
Registration #20	2022-07-04	67.319 mi
Registration #21	2023-07-06	70.430 mi
Registration #22	2024-07-08	73.541 mi
Registration #23	2025-07-10	76.652 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	998 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	G4HD3700955