





report date: 2024-03-28

General information

| Make | HYUNDAI |
|---------------------|-------------------|
| Model | TUCSON GDI SE NAV |
| Colour | White |
| Year of manufacture | 2019 |
| Top speed | 113 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 130 BHP |
|-------------------------|---------------------|
| Max. torque | 161 Nm at 4.850 rpm |
| Engine capacity | 1.591 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 34.4 mpg |
| Consumption extra urban | 44.1 mpg |
| Consumption combined | 34.9 mpg |
| CO2 emission | 162 g/km |
| CO2 label | G |



CarCheck.co.uk page 1/11



report date: 2024-03-28


Internet history

Entry 1

Date 2022-02-22

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

| B 4 | \sim $-$ | | |
|-------|-------------|------|--------|
| 10.71 | $^{\prime}$ | hic | tory |
| 101 | C I | 1115 | I OI V |
| | • | | , |

| MOT expiry date | 2024-07-10 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 12 |
| Total items failed | 2 |

| MOT #4 | 2023-07-10 12:23 |
|------------------|------------------|
| MOT test number | 873169251817 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-10 |

| MOT #3 | 2022-07-11 08:06 |
|-----------------|------------------|
| MOT test number | 520747264232 |
| Result | ✓ Passed |

| MOT #2 | | 2022-02-07 08:46 |
|----------|-----------------------------------------------------------------------------|------------------|
| MOT test | number | 220823404001 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | TPMS light on | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #1 2022-02-04 16:11

MOT test number 968883363189

Result X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice TPMS light on

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 July |
|------------------|--------------------|
| Days left | 63 |
| MOT expiry date | 10 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | 1 |
| First licence fee (12 months) | £ 645,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



faste since

CF68GYY

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this HYUNDAI had different number plates.

CarCheck.co.uk page 8/11



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Courts at info | |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2019-01-29 |
| Last registration | 2023-07-10 |
| Complete history | See info |



| Registration #1 | 2019-01-29 | 18 mi |
|-----------------|------------|--------------|
| | 2022-02-04 | |
| Registration #2 | | 11.515 mi |
| Registration #3 | 2022-02-07 | 11.515 mi |
| Registration #4 | | 11.777 es |
| Registration #5 | | 71.777 66 |
| Registration #6 | | 111.7777 mag |

More info >

page 10/11 CarCheck.co.uk



Car features

The HYUNDAI factory car options list is only available in the premium report. S0225 S0295 S0482 S0501 S0566

View the complete HYUNDAI factory list for this vehicle here.

More info >

Safety ratings

S0567 S0569

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 86% |
| Children | 85% |
| Pedestrian | 71% |
| Safety systems | 71% |
| Overall rating | 80% |
| Video | see crash video |



Dimensions & weight

| Width | 1850 mm |
|---------------------|---------|
| Height | 1650 mm |
| Length | 4475 mm |
| Wheel base | 2670 mm |
| Kerb weight | 1414 kg |
| Max. allowed weight | 2030 kg |

Additional information

| Fuel tank capacity | 62 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

Number of axles 2

Engine number G4FDKZ811474