





report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	B-CLASS B180 CDI BLUEEFFICIENCY SPORT
Colour	White
Year of manufacture	2012
Top speed	118 mph
0 - 100 km/h	9.5 seconds
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	100 kW / 136 HP / 109 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	121 g/km
CO2 label	D



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-07-19

Pictures 16

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-10-03
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	16
Total items failed	3

MOT #12		2023-10-04 15:49
MOT test	number	652493624391
Result		✓ Passed
Next expi	ry date	2024-10-03
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Slight play both inner rack ends	

MOT #11		2023-10-04 13:03
MOT test	number	595909751820
Result		× Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Slight play both inner rack ends		
DANGER	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #10	2022-09-20 14:12
MOT test number	673544807460
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #9 2021-09-21 13:26

MOT test number 860637242981

Result \rightarrow Passed

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Play in steering rack inner joint(s)

MOT #8 2020-12-23 09:19

MOT test number 867460911613

Result ✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7 2020-12-22 13:15

MOT test number 195197206392

Result X Failed

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MAJOR Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6 2019-12-17 15:03

MOT test number 689641020660

Result ✓ Passed

MOT #5 2018-12-21 15:28

MOT test number 860190683988

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources

(4.7.1 (b) (i))

CarCheck.co.uk page 4/12



Result

Fail

Result

Advice

HG62JJV report date: 2024-03-29

X Failed

Passed

MOT #4 2017-12-21 10:42 **MOT** test number 230823795650

Result ✓ Passed

Advice Covers and under-trays obscuring view

MOT #3 2017-12-20 15:13 **MOT** test number 661261457367

Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g) Covers and under-trays obscuring view

Fail Nearside Front Inner Road wheel cracked in several places (4.2.A.1a)

Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail

MOT #2 2016-12-20 09:13 **MOT test number** 482241318696

Advice Covers trays fitted

MOT #1 2015-11-30 11:55

MOT test number 559945563135

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	3 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12




Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



More info >

Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How may MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here.	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK OK
Plate since	

CarCheck.co.uk page 9/12



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-12-13
Last registration	2023-10-04
Complete history	See info



Registration #1	2012-12-13	7 mi
Registration #2	2015-11-30	34.536 mi
Registration #3	2016-12-20	40.827 mi
Registration #4	2017-12-20	48.279 mi
Registration #5	2017-12-21	48.279 mi
Registration #6	2018-12-21	55.551 mi
Registration #7	2019-12-17	61.660 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91,700 esi

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	97%
Children	81%
Pedestrian	56%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2010 mm
Height	1557 mm
Length	4359 mm
Wheel base	2699 mm
Kerb weight	1375 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
CarChaglegande	nogo 12/12

CarCheck.co.uk page 12/12

Number of axles	2
Engine number	65190131083436