



report date: 2024-03-28

General information

| | |
|---------------------|----------------------------|
| Make | CITROEN |
| Model | XSARA HDI DESIRE 2 PICASSO |
| Colour | Green |
| Year of manufacture | - |
| Top speed | 109 mph |
| 0 - 60 mph | 12.6 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 90 BHP |
| Max. torque | 205 Nm at 1.900 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 40.4 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 51.4 mpg |




LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-07-20 |
| Pictures | 5 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|------------------|------------------|
| MOT #23 | 2021-07-13 11:06 |
| MOT test number | 135914363133 |
| Result | ✓ Passed |
| Next expiry date | 2022-07-20 |

| | |
|-----------------|------------------|
| MOT #22 | 2020-07-21 16:34 |
| MOT test number | 264131868339 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #21 | 2020-07-21 11:29 |
| MOT test number | 387145136947 |
| Result | ✗ Failed |

Fail Nearside Front Brake pipe excessively corroded (1.1.11 (c))

Fail Offside Front Brake pipe excessively corroded (1.1.11 (c))

| | |
|-----------------|------------------|
| MOT #20 | 2019-07-17 15:02 |
| MOT test number | 152929938268 |
| Result | ✓ Passed |

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge worn outer edge (5.2.3 (e))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #19** 2018-09-19 12:25**MOT test number** 472595209513**Result** ✗ Failed

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Front Direction indicator not working (4.4.1 (a) (ii))
- Fail** Offside Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))
- Fail** Front Registration plate incorrect (0.1 (c))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Nearside Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))
- Fail** Exhaust has a major leak of exhaust gases Back box (6.1.2 (a))
- Fail** Rear Registration plate incorrect (0.1 (c))

MOT #18 2016-10-15 14:37**MOT test number** 527488891365**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit worn outer edge (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit worn outer edge (4.1.E.1)

MOT #17 2015-10-19 13:14**MOT test number** 168528130578**Result** ✓ Passed

**MOT #16** 2015-10-15 14:39**MOT test number** 140688882562**Result** ✗ Failed**Fail** Offside Front position lamp(s) has less than 50% of the light sources illuminating (1.1.A.3b)**MOT #15** 2014-11-17 08:54**MOT test number** 507811724373**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #14** 2014-11-11 16:23**MOT test number** 248005114346**Result** ✗ Failed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Front registration plate character(s) incorrectly spaced (6.3.4a)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Offside Seat belt anchorage prescribed area is excessively corroded (5.2.6)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Rear registration plate character(s) incorrectly spaced (6.3.4a)**Fail** Nearside Seat belt anchorage prescribed area is excessively corroded (5.2.6)**MOT #13** 2013-10-15 14:34**MOT test number** 486278583210**Result** ✓ Passed

**MOT #12** 2013-10-15 14:34**MOT test number** 607648783201**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**MOT #11** 2012-11-05 15:27**MOT test number** 495050812446**Result** ✓ Passed**MOT #10** 2012-11-05 14:28**MOT test number** 645930512328**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #9** 2011-11-03 16:34**MOT test number** 647437001349**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)**Advice** Nearside Side repeater slightly discoloured (1.4.A.2f)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Side repeater slightly discoloured (1.4.A.2f)**Advice** Nearside front brake juddering slightly (3.7.A.2b)



| | |
|-------------------------|---|
| MOT #8 | 2011-11-03 16:34 |
| MOT test number | 706617901344 |
| Result | ✗ Failed |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Rear Exhaust has a minor leak of exhaust gases (7.1.2) |
| Advice | Offside Side repeater slightly discoloured (1.4.A.2f) |
| Advice | Nearside front brake juddering slightly (3.7.A.2b) |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Nearside Rear Brake hose slightly deteriorated (3.6.B.4d) |
| Advice | Nearside Side repeater slightly discoloured (1.4.A.2f) |
| Pass with rectification | Offside Stop lamp not working (1.2.1b) |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |

| | |
|-----------------|------------------|
| MOT #7 | 2010-10-27 11:28 |
| MOT test number | 102650200398 |
| Result | ✓ Passed |

**MOT #6** 2010-10-26 11:18**MOT test number** 820889090244**Result** ✗ Failed**Fail** Offside Front Direction indicators not working (1.4.A.2c)**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Notice** Off side rear tyre starting to perish**Fail** Front registration plate character(s) incorrectly spaced (6.3.4a)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Rear Exhaust system not adequately supported (7.1.1)**Fail** Rear registration plate character(s) incorrectly spaced (6.3.4a)**MOT #5** 2009-10-14 18:12**MOT test number** 174937289260**Result** ✗ Failed**Pass with rectification** Rear Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2009-10-14 18:12**MOT test number** 624187489276**Result** ✓ Passed**MOT #3** 2008-11-18 14:47**MOT test number** 634093028371**Result** ✓ Passed**MOT #2** 2007-12-20 14:35**MOT test number** 844734557302**Result** ✓ Passed



MOT #1

2007-12-20 11:37

MOT test number

480314557447

Result

✗ Failed

Fail

Rear registration plate character(s) incorrectly spaced (6.3.4a)

Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Offside Front Brake pad(s) wearing thin (3.5.1g)

Fail

Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Fail

Centre Front registration plate character(s) incorrectly spaced (6.3.4a)

Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Nearside Front Brake pad(s) wearing thin (3.5.1g)

Fail

Nearside Rear Direction indicator incorrect colour (1.4.A.2f)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2019-09-29 |
| Current registration | |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 21 |
| First mileage registration | 2004-11-19 |
| Last registration | 2021-07-13 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2004-11-19 | 13 mi |
| Registration #2 | 2007-12-20 | 25.760 mi |
| Registration #3 | 2007-12-20 | 25.760 mi |
| Registration #4 | 2009-10-14 | 33.769 mi |
| Registration #5 | 2010-10-26 | 38.488 mi |
| Registration #6 | 2010-10-27 | 38.488 mi |
| Registration #7 | 2011-11-03 | 41.703 mi |
| Registration #8 | 2012-11-05 | 44.677 mi |
| Registration #9 | 2012-11-05 | 44.679 mi |
| Registration #10 | 2013-10-15 | 47.501 mi |
| Registration #11 | 2014-11-11 | 54.235 mi |
| Registration #12 | 2015-05-20 | 55.277 mi |
| Registration #13 | 2015-05-20 | 55.277 mi |
| Registration #14 | 2015-05-20 | 55.277 mi |
| Registration #15 | 2015-05-20 | 55.277 mi |
| Registration #16 | 2015-05-20 | 55.277 mi |
| Registration #17 | 2015-05-20 | 55.277 mi |
| Registration #18 | 2015-05-20 | 55.277 mi |
| Registration #19 | 2015-05-20 | 55.277 mi |
| Registration #20 | 2015-05-20 | 55.277 mi |
| Registration #21 | 2015-05-20 | 55.277 mi |

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

| | |
|-------------|---------|
| Width | 1751 mm |
| Height | 1637 mm |
| Length | 4276 mm |
| Wheel base | 2760 mm |
| Kerb weight | 1300 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Engine number | DYRZ4017511 |