



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX20 CLASSIC
Colour	White
Year of manufacture	2012
Top speed	104 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	137 Nm at 5.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	50.4 mpg
CO2 emission	130 g/km
CO2 label	D







Internet history

Entry 1

Date	2021-09-24
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-19
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	14
Total items failed	12

MOT #12 2023-10-16 13:14

MOT test number 455847182631

Result ✓ Passed

Next expiry date 2024-10-19

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #11 2023-10-16 09:23

MOT test number 501057479466

Result ✗ Failed**Fail** Nearside Rear Stop lamp(s) with a multiple light source more than 1/2 not functioning (4.3.1 (a) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Fail** Exhaust emissions carbon monoxide content excessive (8.2.1.2 (b))**Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #10** 2022-10-20 16:10**MOT test number** 729579779963**Result** ✓ Passed**MOT #9** 2022-10-20 10:27**MOT test number** 542763788240**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Rear Nail in tyre**MOT #8** 2021-09-06 15:02**MOT test number** 239461877418**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Play in steering rack inner joint(s)

**MOT #7** 2021-09-06 08:56**MOT test number** 414249887632**Result** ✗ Failed

- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Play in steering rack inner joint(s)
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #6 2019-06-25 13:59**MOT test number** 634484339499**Result** ✓ Passed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #5 2018-07-31 09:18**MOT test number** 634363178586**Result** ✓ Passed**MOT #4** 2017-06-22 15:38**MOT test number** 439036618147**Result** ✓ Passed



MOT #3	2016-11-03 12:05
MOT test number	638232355261
Result	✓ Passed
Advice	Slight wear in nearside front droplink

MOT #2	2015-11-02 18:20
MOT test number	725416163805
Result	✓ Passed

MOT #1	2015-04-24 12:00
MOT test number	309344115112
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
19 October 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	19 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-04-30
Last registration	2023-10-16
Complete history	See info



Registration #1	2012-04-30	28 mi
Registration #2	2015-04-24	17.780 mi
Registration #3	2015-11-02	20.083 mi
Registration #4	2016-11-03	25.276 mi
Registration #5	2017-06-22	29.600 mi
Registration #6	2018-07-31	32.248 mi
Registration #7	2019-06-25	35.126 mi
Registration #8	2019-06-25	35.126 mi
Registration #9	2019-06-25	35.126 mi
Registration #10	2019-06-25	35.126 mi
Registration #11	2019-06-25	35.126 mi
Registration #12	2019-06-25	35.126 mi
Registration #13	2019-06-25	35.126 mi
Registration #14	2019-06-25	35.126 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1268 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FACZ519415