



V20JPW

report date: 2024-03-28

General information

Make	MAZDA
Model	RX-8 RX-8 PZ
Colour	Blue
Year of manufacture	2007
Top speed	146 mph
0 - 60 mph	6.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	231 BHP
Max. torque	211 Nm at 5.500 rpm
Engine capacity	2.616 cc
Cylinders	2
Fuel type	Petrol
Consumption city	18.1 mpg
Consumption extra urban	32.5 mpg
Consumption combined	25.2 mpg
CO2 emission	284 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-06-05
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-01-22
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	35
Total items failed	5

MOT #18 2024-02-06 16:58

MOT test number 759263130642

Result ✗ Failed

**MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #17 2023-01-23 12:28

MOT test number 584934156195

Result ✓ Passed

**Advice** Nearside & offside front headlamps deteriorating

**Advice** Front exhaust heat shields loose & rattling

MOT #16 2022-01-07 15:39

MOT test number 532068139454

Result ✓ Passed

**MOT #15** 2021-12-02 12:00**MOT test number** 993713285788**Result** ✗ Failed**MAJOR** Headlamp levelling device inoperative Broken level sensor bracket (4.1.5 (a))**MAJOR** Offside Headlamp aim too low (4.1.2 (a))**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Nearside Headlamp aim too low (4.1.2 (a))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #14** 2020-12-16 17:34**MOT test number** 757798967450**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #13**

2020-12-09 10:42

**MOT test number**

475842990972

**Result****✗ Failed**

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 0.4mm useable tread remaining 225/4518 (5.2.3 (e))

**Advice** Items removed from driver's view prior to test

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 0.4mm useable tread remaining 225/4518 (5.2.3 (e))

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Pass with rectification** Rear Registration plate inscription illegible (0.1 (b))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12**

2019-06-14 14:04

**MOT test number**

215705650845

**Result****✓ Passed****MOT #11**

2019-06-14 08:22

**MOT test number**

181685335015

**Result****✗ Failed**

**MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))

**MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))

**MAJOR** Offside Rear Brake pipe excessively corroded to flex (1.1.11 (c))

**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))

**MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #10** 2017-07-17 14:42**MOT test number** 413157623859**Result** ✓ Passed**MOT #9** 2016-07-18 09:35**MOT test number** 150716349983**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2016-07-18 09:35**MOT test number** 688383342315**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2015-07-28 10:13**MOT test number** 355599105431**Result** ✓ Passed**MOT #6** 2014-07-21 12:07**MOT test number** 376422704269**Result** ✓ Passed

**MOT #5** 2013-07-19 11:07**MOT test number** 836910603264**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2012-07-05 16:04**MOT test number** 288827382196**Result** ✓ Passed**MOT #3** 2011-07-22 14:48**MOT test number** 129083301263**Result** ✓ Passed**MOT #2** 2011-07-22 12:46**MOT test number** 257773801271**Result** ✗ Failed**Fail** Offside Rear Anti-roll bar linkage insecure (2.4.G.1)**Fail** Nearside Front Anti-roll bar linkage insecure (2.4.G.1)**MOT #1** 2010-07-14 11:30**MOT test number** 474665190154**Result** ✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
9 February 2024

✕  
MOT

Expired:  
22 January 2024

Tax status	Expired at 9 February 2024
Days left	80 days too late
MOT expiry date	22 January 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-07-27
Last registration	2024-02-06
Complete history	<a href="#">See info</a>



Registration #1	2007-07-27	13 mi
Registration #2	2010-07-14	17.240 mi
Registration #3	2011-07-22	28.756 mi
Registration #4	2011-07-22	28.756 mi
Registration #5	2012-07-05	39.076 mi
Registration #6	2013-07-19	42.304 mi
Registration #7	2014-07-21	43.530 mi
Registration #8	2015-07-28	48.308 mi
Registration #9	2016-07-18	52.613 mi
Registration #10	2016-07-18	52.613 mi
Registration #11	2016-07-18	52.613 mi
Registration #12	2016-07-18	52.613 mi
Registration #13	2016-07-18	52.613 mi
Registration #14	2016-07-18	52.613 mi
Registration #15	2016-07-18	52.613 mi
Registration #16	2016-07-18	52.613 mi
Registration #17	2016-07-18	52.613 mi
Registration #18	2016-07-18	52.613 mi
Registration #19	2016-07-18	52.613 mi
Registration #20	2016-07-18	52.613 mi

More info >



Dimensions & weight

Width	1770 mm
Height	1340 mm
Length	4430 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1815 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	13B 504499