





### General information

Make	CITROEN
Model	DS3 PURETECH FLAIR
Colour	White
Year of manufacture	2015
Top speed	106 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	80 BHP	0 < 101 A
Max. torque	118 Nm at 2.750 rpm	101 - 120 <sup>B</sup>
Engine capacity	1.200 cc	121 - 140
Cylinders	3	141 - 165 F
Fuel type	Petrol	166 - 185
Consumption city	50.4 mpg	186 - 225 J
Consumption extra urban	70.6 mpg	225+
Consumption combined	61.4 mpg	
CO2 emission	107 g/km	
CO2 label	В	





# Internet history

Entry 1

Date


2021-09-17

Pictures

Listing price

View report

9



source: cargurus.co.uk



# MOT history

MOT expiry date	2025-04-06
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	23
Total items failed	6

MOT #11	2024-04-06 08:03
MOT test number	606380374883
Result	✓ Passed
Next expiry date	2025-04-06
Advice Engine oil level low	
Advice Rear silencer heat shield loose	
Advice Emitting blue smoke from exhaust after engine idle	
Advice Tyre pressure warning light on [no obvious tyre defects]	

MOT #10	2023-04-04 08:54
MOT test number	914696191570
Result	✓ Passed

MOT #9	2022-04-04 15:15
MOT test number	346116683859
Result	✓ Passed

MOT #8	2022-04-04 10:59
MOT test number	246435690191
Result	🗙 Failed
<b>Fail</b> Exhaust system insecure (6.1.2 (a))	





MOT #7	2021-04-07 13:05
MOT test number	767539181663
Result	✓ Passed
MOT #6	2021-04-06 09:50
MOT test number	552538261441
Result	🗙 Failed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
<b>Fail</b> Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail         Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
<b>Advice</b> Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #5		2020-03-25 12:29
MOT test	number	203759388670
Result		✓ Passed
Advice Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Rear Exhaust mounting defective (6.1.2 (a))	



<b>DE15</b>	LWJ
report date:	2024-03-29

MOT #4			2020-03-25 12:29
MOT test	number		462949536857
Result			🗙 Failed
Advice	Nearside Rear Tyre	e slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Exhaust mou	nting defective (6.1.2 (a))	
Advice	Offside Rear Tyre s	slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Pass wit	h rectification	learside Headlamp aim projected beam image is obviou	sly incorrect (4.1.2 (c))

MOT #3		2019-03-27 12:30
MOT test	number	741946190713
Result		✓ Passed
Advice	Rear Exhaust mounting defective (6.1.2 (a))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing cracking between	tread (5.2.3 (d) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing cracking between t	read (5.2.3 (d) (ii))

МОТ #2	2019-03-26 09:36
MOT test number	129593639784
Result	🗙 Failed
<b>Fail</b> Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing cracking betwee	en tread (5.2.3 (d) (ii))
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Rear Exhaust mounting defective (6.1.2 (a))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking betw	een tread (5.2.3 (d) (ii))
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.1	.4 (a) (ii))





MOT #1	2018-03-13 11:08
MOT test number	795019397316
Result	✓ Passed



Tax & MOT check

X Untaxed Tax expired: 20 April 2024	✓ MOT Expires: 6 April 2025
Tax status	Expired at 20 April 2024
Days left	9 days too late
MOT expiry date	6 April 2025
Full MOT history	See MOT history
Tax calculation	
Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-

Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	VAMPL
Date	······································
Category	AMP
Туре	

#### Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

*******	
**********	
********	
******	
**********	
********	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-03-31
Last registration	2024-04-06
Complete history	See info



Registration #1	2015-03-31	20 mi
Registration #2	2018-03-13	24.203 mi
Registration #3	2019-03-26	34.249 mi
Registration #4	2019-03-27	34.251 mi
Registration #5	2020-03-25	42.486 mi
Registration #6	2020-03-25	42.486 mi
Registration #7	2021-04-06	48.660 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		10.000 and
-		





# Safety ratings

NCAP rating	****
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	see crash video



Dimensions & weight	
Width	1729 mm
Height	1480 mm
Length	4157 mm
Wheel base	2595 mm
Kerb weight	965 kg
Max. allowed weight	1500 kg
Additional information	
Additional information Fuel tank capacity	50 l
	50 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5