



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I30 T-GDI SE NAV
Colour	Silver
Year of manufacture	2018
Top speed	117 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	171 Nm at 4.000 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 2



Date	2022-05-10
Pictures	24
Listing price	View report



source: yesauto.com

Entry 1

Date	2022-05-07
Pictures	25
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-04-29
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	16
Total items failed	4

MOT #5	2024-04-27 08:59
MOT test number	502089823038
Result	✓ Passed
Next expiry date	2025-04-29
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #4	2023-04-28 15:11
MOT test number	885916145911
Result	✓ Passed
Minor	Rear Windscreen wiper blade defective split (3.4 (b) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear exhaust box and sub-frame covered in oil
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear tyre stepping inner edge
Advice	Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i))

**MOT #3** 2023-04-28 13:06**MOT test number** 492897705652**Result** ✗ Failed

- Fail** Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Rear exhaust box and sub-frame covered in oil
- Advice** Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Rear Windscreen wiper blade defective split (3.4 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Rear tyre stepping inner edge
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #2 2022-04-02 08:58**MOT test number** 338453511191**Result** ✓ Passed**MOT #1** 2021-04-30 13:53**MOT test number** 549529607708**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
29 April 2024

Tax status	Valid until 1 May
Days left	2
MOT expiry date	29 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EX18NWB
Plate since	2019-03-29
Current registration	EX18NWB
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-06-01
Last registration	2024-04-27
Complete history	See info



Registration #1	2018-06-01	26 mi
Registration #2	2021-04-30	15.546 mi
Registration #3	2022-04-02	20.162 mi
Registration #4	2023-04-02	25.277 mi
Registration #5	2023-04-02	25.277 mi
Registration #6	2023-04-02	25.277 mi
Registration #7	2023-04-02	25.277 mi
Registration #8	2023-04-02	25.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	64%
Safety systems	68%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1425 mm
Length	4455 mm
Wheel base	2650 mm
Kerb weight	1342 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G3LCJP021400