




General information

Make	CITROEN
Model	DS5 HDI DSTYLE
Colour	Black
Year of manufacture	2013
Top speed	134 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	68.9 mpg
Consumption combined	57.7 mpg
CO2 emission	133 g/km
CO2 label	E





report date: 2024-03-29

**MOT history**

MOT expiry date	2024-09-06
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	33
Total items failed	19

MOT #13	2023-09-07 11:56
MOT test number	122980635248
Result	✓ Passed
Next expiry date	2024-09-06

MOT #12	2023-09-05 08:47
MOT test number	552385032735

Result	✗ Failed
---------------	----------

- Fail** Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Offside Front Headlamp aim too far to the left (4.1.2 (a))
- Fail** Offside Front Anti-roll bar linkage has an unsafe modification (5.3.3 (c) (i))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #11** 2022-09-02 08:57**MOT test number** 639091463645**Result** ✓ Passed**Advice** Nearside Front Track rod end slightly misaligned (2.1.3 (e))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Outer Drive shaft joint worn, but not excessively (6.1.7 (c) (i))**MOT #10** 2021-09-01 10:02**MOT test number** 626654078448**Result** ✓ Passed**MOT #9** 2020-11-26 15:55**MOT test number** 102941605705**Result** ✓ Passed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #8** 2020-11-21 11:06**MOT test number** 106642592214**Result** ✗ Failed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Nearside Front Hydraulic brake calliper inadequately mounted (1.1.16 (c) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #7**

2019-12-20 15:02

MOT test number

559276090975

Result

✓ Passed

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Advice** Nearside Front Outer pad retaining device missing

MOT #6

2019-12-17 16:05

MOT test number

751860864629

Result

✗ Failed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))
- Pass with rectification** Nearside Front Headlamp aim projected beam image is obviously incorrect bulb incorrectly fitted (4.1.2 (c))
- Advice** Nearside Front Outer pad retaining device missing
- Fail** Offside Front Suspension arm pin or bush excessively worn wishbone, rear bush (5.3.4 (a) (i))
- Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Suspension arm pin or bush excessively worn front wishbone, rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #5**

2018-12-17 15:00

MOT test number

334060983941

Result

✓ Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 1.6 (5.2.3 (e))**MOT #4**

2018-12-17 13:45

MOT test number

325077691648

Result

✗ Failed

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Offside Rear Outer Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 1.6 (5.2.3 (e))**MOT #3**

2017-08-24 13:35

MOT test number

535162484543

Result

✓ Passed

Advice Nearside Front tyre wearing on edges**Advice** Offside Front tyre wearing on edges



MOT #2	2017-08-22 12:50
MOT test number	733864120792
Result	✗ Failed
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Advice	Offside Front tyre wearing on edges
Advice	Nearside Front tyre wearing on edges

MOT #1	2016-07-05 12:41
MOT test number	658242525003
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
6 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	6 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-07-30
Last registration	2023-09-07
Complete history	See info



Registration #1	2013-07-30	22 mi
Registration #2	2016-07-05	30.049 mi
Registration #3	2017-08-22	49.565 mi
Registration #4	2017-08-24	49.637 mi
Registration #5	2018-12-17	69.214 mi
Registration #6	2018-12-17	69.221 mi
Registration #7	2019-12-17	83.418 mi
Registration #8	2019-12-20	83.446 mi
Registration #9	2020-05-20	95.377 mi
Registration #10	2020-05-20	95.377 mi
Registration #11	2020-05-20	95.377 mi
Registration #12	2020-05-20	95.377 mi
Registration #13	2020-05-20	95.377 mi
Registration #14	2020-05-20	95.377 mi
Registration #15	2023-09-07	95.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	83%
Pedestrian	40%
Safety systems	97%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1850 mm
Height	1508 mm
Length	4530 mm
Wheel base	2727 mm
Kerb weight	1540 kg
Max. allowed weight	2130 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYZE4069368