



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I40 CRDI PREMIUM BLUE DRIVE
Colour	Blue
Year of manufacture	2014
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2024-05-24
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	33
Total items failed	8

## MOT #12 2023-05-22 09:32

MOT test number 566353987734

Result ✓ Passed

Next expiry date 2024-05-24

- Advice** Chip a zone
- Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

## MOT #11 2022-05-23 11:04

MOT test number 430484209547

Result ✓ Passed

- Advice** Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Chip a zone

## MOT #10 2021-05-25 15:31

MOT test number 430371399331

Result ✓ Passed

- Advice** Front offside and front nearside tyres worn smooth inner edges

**MOT #9**

2021-05-25 10:48

**MOT test number**

303736410511

**Result****✗ Failed****Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Advice** Front offside and front nearside tyres worn smooth inner edges**MOT #8**

2020-09-10 09:05

**MOT test number**

854916812811

**Result****✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn badly in side edge 2056016 (5.2.3 (e))**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn badly in side edge 2056016 (5.2.3 (e))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #7**

2020-09-10 09:05

**MOT test number**

338890928837

**Result****✗ Failed****Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn badly in side edge 2056016 (5.2.3 (e))**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn badly in side edge 2056016 (5.2.3 (e))

**MOT #6** 2019-09-19 14:33**MOT test number** 346931650265**Result** ✓ Passed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both worn and lipped (1.1.14 (a) (ii))

**Advice** TPMS light on

**MOT #5** 2019-09-19 09:01**MOT test number** 372945154004**Result** ✗ Failed

**Fail** Offside Rear Service brake excessively fluctuating (1.2.1 (e))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both worn and lipped (1.1.14 (a) (ii))

**Advice** TPMS light on

**Fail** Nearside Rear Service brake excessively fluctuating (1.2.1 (e))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both worn (1.1.14 (a) (ii))

**MOT #4** 2018-09-28 16:13**MOT test number** 905544605262**Result** ✓ Passed

**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #3**

2018-09-28 16:13

**MOT test number**

632190500844

**Result****✗ Failed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2**

2018-09-26 11:04

**MOT test number**

870807799313

**Result****✗ Failed****Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Wheel bearing has excessive play (5.1.3 (a) (i))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))**MOT #1**

2017-10-30 11:52

**MOT test number**

823904124388

**Result****✓ Passed**



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
24 May 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	367
<b>MOT expiry date</b>	24 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-10-31
Last registration	2023-05-22
Complete history	<a href="#">See info</a>



Registration #1	2014-10-31	26 mi
Registration #2	2017-10-30	98.173 mi
Registration #3	2018-09-26	105.744 mi
Registration #4	2018-09-28	105.772 mi
Registration #5	2018-09-28	105.772 mi
Registration #6	2019-09-19	112.148 mi
Registration #7	2019-09-19	112.148 mi
Registration #8	2019-09-19	112.148 mi
Registration #9	2019-09-19	112.148 mi
Registration #10	2019-09-19	112.148 mi
Registration #11	2019-09-19	112.148 mi
Registration #12	2019-09-19	112.148 mi
Registration #13	2019-09-19	112.148 mi
Registration #14	2019-09-19	112.148 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1638 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D4FDEU465097