




report date: 2024-03-29

General information

Make	VOLVO
Model	C70 T5 SE LUX
Colour	Grey
Year of manufacture	2007
Top speed	146 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	220 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	19.8 mpg
Consumption extra urban	39.2 mpg
Consumption combined	28.8 mpg
CO2 emission	234 g/km
CO2 label	L






Internet history

Entry 1

Date	2021-07-01
Pictures	7
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-06
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	16
Total items failed	5

MOT #17	2023-09-07 15:46
MOT test number	850217738432
Result	✓ Passed
Next expiry date	2024-09-06

MOT #16	2023-08-19 11:37
MOT test number	413494894017
Result	✗ Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Rear Exhaust has a major leak of exhaust gases rear box (6.1.2 (a))

MOT #15	2022-08-04 09:10
MOT test number	670193022536
Result	✓ Passed
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Rear heat shield partially insecure
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #14** 2021-08-23 10:00**MOT test number** 248040844280**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #13** 2021-01-29 12:55**MOT test number** 608368683071**Result** ✓ Passed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12** 2020-01-24 11:49**MOT test number** 767462143697**Result** ✓ Passed**MOT #11** 2020-01-20 11:56**MOT test number** 259983822789**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))



MOT #10	2019-01-08 10:26
----------------	------------------

MOT test number	870290147668
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2018-01-30 14:12
---------------	------------------

MOT test number	773346744768
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2017-01-19 15:26
---------------	------------------

MOT test number	526954941041
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2016-01-25 12:43
---------------	------------------

MOT test number	915737844196
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2015-01-15 14:44
---------------	------------------

MOT test number	207675415047
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2014-01-11 11:34
---------------	------------------

MOT test number	688471014027
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2013-01-12 12:42
---------------	------------------

MOT test number	136122613416
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	O/s/f outtor tyre wall damaged
---------------	--------------------------------



MOT #3	2012-01-17 17:17
MOT test number	617147612034
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2011-01-07 15:06
MOT test number	979977301006
Result	✓ Passed

MOT #1	2010-01-14 14:50
MOT test number	652064910023
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
30 January 2024

✓

MOT

Expires:
6 September 2024

Tax status	Expired at 30 January 2024
Days left	91 days too late
MOT expiry date	6 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-01-31
Last registration	2023-09-07
Complete history	See info



Registration #1	2007-01-31	10 mi
Registration #2	2010-01-14	17.604 mi
Registration #3	2011-01-07	25.812 mi
Registration #4	2012-01-17	34.102 mi
Registration #5	2013-01-12	42.053 mi
Registration #6	2014-01-11	50.052 mi
Registration #7	2015-01-15	57.719 mi
Registration #8	2016-01-25	64.902 mi
Registration #9	2017-01-19	71.959 mi
Registration #10	2018-01-30	78.972 mi
Registration #11	2019-01-20	85.977 mi
Registration #12	2020-01-20	92.977 mi
Registration #13	2021-01-20	99.977 mi
Registration #14	2022-01-20	106.977 mi
Registration #15	2023-01-20	113.977 mi
Registration #16	2024-01-20	120.977 mi
Registration #17	2025-01-20	127.977 mi
Registration #18	2026-01-20	134.977 mi
Registration #19	2027-01-20	141.977 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1987 mm
Height	1400 mm
Length	4582 mm
Wheel base	2640 mm
Kerb weight	1651 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	4021583