



General information

Make	VOLKSWAGEN
Model	GOLF SE TDI
Colour	Blue
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	57.7 mpg
CO2 emission	126 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-06-15
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	17
Total items failed	5

## MOT #14 2023-06-16 13:35

MOT test number 756568702886

Result ✓ Passed

Next expiry date 2024-06-15

- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear lower suspension arms slightly corroded
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

## MOT #13 2023-06-16 10:56

MOT test number 161465654837

Result ✗ Failed

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear lower suspension arms slightly corroded
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inside edge (5.2.3 (e))

**MOT #12** 2022-04-28 12:44**MOT test number** 853022482877**Result** ✓ Passed**Advice** Surface rust on rear suspension arms**MOT #11** 2021-04-22 10:57**MOT test number** 242361701714**Result** ✓ Passed**MOT #10** 2021-01-21 11:41**MOT test number** 104751862792**Result** ✓ Passed**MOT #9** 2021-01-19 16:35**MOT test number** 194099179351**Result** ✗ Failed**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #8** 2020-01-06 10:57**MOT test number** 175840513213**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #7** 2019-01-02 12:32**MOT test number** 340211554423**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #6** 2017-12-12 11:16**MOT test number** 813835472654**Result** ✓ Passed**MOT #5** 2017-12-12 11:16**MOT test number** 829874392006**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #4** 2016-12-01 16:31**MOT test number** 787525129251**Result** ✓ Passed**MOT #3** 2015-12-21 16:41**MOT test number** 580649866297**Result** ✓ Passed**MOT #2** 2014-12-22 11:25**MOT test number** 649086254381**Result** ✓ Passed**Notice** Both front tyre worn inner edge**Notice** Both rear tyre worn inner edge**MOT #1** 2013-12-18 13:14**MOT test number** 438782653327**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
15 June 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	217
<b>MOT expiry date</b>	15 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-07-09
Last registration	2023-06-16
Complete history	<a href="#">See info</a>



Registration #1	2010-07-09	18 mi
Registration #2	2013-12-18	37.529 mi
Registration #3	2014-12-22	50.940 mi
Registration #4	2015-12-21	67.562 mi
Registration #5	2016-12-01	81.123 mi
Registration #6	2017-12-12	95.402 mi
Registration #7	2017-12-12	95.402 mi
Registration #8	2019-01-02	106.946 mi
Registration #9	2019-01-02	106.946 mi
Registration #10	2019-01-02	106.946 mi
Registration #11	2019-01-02	106.946 mi
Registration #12	2019-01-02	106.946 mi
Registration #13	2019-01-02	106.946 mi
Registration #14	2019-01-02	106.946 mi
Registration #15	2019-01-02	106.946 mi
Registration #16	2019-01-02	106.946 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1299 kg
Max. allowed weight	1920 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	CFF 131883