



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	COUPE SIII
Colour	Red
Year of manufacture	2008
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	4 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Engine capacity	1.975 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg
CO2 emission	193 g/km
CO2 label	J






Internet history

Entry 2

Date 2023-12-13

Pictures 8



source: g3remarketing.co.uk

Entry 1

Date 2022-02-05

Pictures 6

Listing price [View report](#)



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-08-14
MOT pass rate	57 %
MOT passed	13
Failed MOT tests	10
Total advice items	66
Total items failed	17

MOT #23	2023-08-15 14:31
MOT test number	541389922890
Result	✓ Passed
Next expiry date	2024-08-14
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #22	2023-07-28 09:05
MOT test number	214571213332
Result	✗ Failed
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
Fail	Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MOT #21** 2022-08-02 15:13**MOT test number** 189317385542**Result** ✓ Passed**Advice** Front Tyre worn close to legal limit/worn on edge x2)(215-45x17w (5.2.3 (e))**Advice** Exhaust noisy (8.1.1 (a))**Minor** Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #20** 2021-07-06 15:33**MOT test number** 697327839477**Result** ✓ Passed**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #19** 2021-07-05 13:11**MOT test number** 296622828797**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #18** 2020-07-17 08:13**MOT test number** 412619894121**Result** ✓ Passed**Advice** Underside corroded**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #17** 2019-05-10 15:08**MOT test number** 954572204798**Result** ✓ Passed**Advice** Exhaust system corroded**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #16** 2019-05-10 10:56**MOT test number** 668191642760**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed 215/45/17 (5.2.3 (d) (ii))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Exhaust system corroded**MOT #15** 2018-05-15 14:42**MOT test number** 596237415710**Result** ✓ Passed**MOT #14** 2018-05-15 08:45**MOT test number** 967759527977**Result** ✗ Failed**Fail** Nearside Front Headlamp aim too low (1.8)**Fail** Offside Front Headlamp aim too low (1.8)

**MOT #13**

2017-05-18 12:30

**MOT test number**

567589810975

**Result**

✓ Passed

**Advice** Nearside Front Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Nearside Front front brake fluctuating, but not excessively (3.7.B.3)**MOT #12**

2016-05-27 11:25

**MOT test number**

727280331102

**Result**

✓ Passed

**Advice** Nearside Rear tyre wearing on inner edge of tread & cracking**Advice** Offside Front coil spring corroded (2.4.C.1b)**Advice** Exhaust deteriorated**Advice** Unable to fully check outer sills due to plastic covers**Advice** Nearside Front coil spring corroded (2.4.C.1b)**MOT #11**

2016-05-27 11:25

**MOT test number**

138611540195

**Result**

✗ Failed

**Advice** Unable to fully check outer sills due to plastic covers**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Offside Front coil spring corroded (2.4.C.1b)**Advice** Nearside Rear tyre wearing on inner edge of tread & cracking**Advice** Nearside Front coil spring corroded (2.4.C.1b)**Advice** Exhaust deteriorated

**MOT #10**

2015-05-08 10:43

**MOT test number**

939348725183

**Result**

✓ Passed

- Advice** Offside Front coil spring corroded (2.4.C.1b)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front coil spring corroded (2.4.C.1b)
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #9**

2015-05-08 10:43

**MOT test number**

649608725171

**Result**

✗ Failed

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front coil spring corroded (2.4.C.1b)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front coil spring corroded (2.4.C.1b)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)

**MOT #8**

2014-05-14 09:28

**MOT test number**

499294134106

**Result**

✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Items removed from driver's view prior to test
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #7**

2014-05-14 09:28

**MOT test number**

678174234152

**Result**

✗ Failed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Items removed from driver's view prior to test
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



**MOT #6** 2013-05-16 16:47**MOT test number** 678906333171**Result** ✓ Passed**Advice** Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2013-05-16 16:47**MOT test number** 677086433110**Result** ✗ Failed**Pass with rectification** Nearside Rear position lamp(s) has less than 50% of the light sources illuminating (1.1.A.3b)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Nearside Stop lamp has less than 50% of the light sources illuminating (1.2.1b)**Advice** Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2012-05-21 12:44**MOT test number** 428852842102**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Osf tyre worn on inner edge rest of tread ok at present

**MOT #3** 2012-05-21 12:44**MOT test number** 168782042141**Result** ✗ Failed**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Osf tyre worn on inner edge rest of tread ok at present**MOT #2** 2011-05-23 11:03**MOT test number** 549773441123**Result** ✓ Passed**MOT #1** 2011-05-23 10:41**MOT test number** 158443641134**Result** ✗ Failed**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
14 August 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	185
<b>MOT expiry date</b>	14 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	J
<b>Single payment (12 months)</b>	£ 365,00,-
<b>Single six month payment</b>	£ 200,75,-
<b>Total payable by 12 monthly instalments</b>	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-05-30
Last registration	2023-08-15
Complete history	<a href="#">See info</a>



Registration #1	2008-05-30	8 mi
Registration #2	2011-05-23	23.811 mi
Registration #3	2011-05-23	23.811 mi
Registration #4	2012-05-21	31.273 mi
Registration #5	2013-05-16	37.856 mi
Registration #6	2014-05-14	46.329 mi
Registration #7	2015-05-08	53.505 mi
Registration #8	2016-05-27	60.703 mi
Registration #9	2016-05-27	60.703 mi
Registration #10	2017-05-18	66.913 mi
Registration #11	2018-05-15	73.671 mi
Registration #12	2019-05-20	80.277 mi
Registration #13	2019-05-20	80.277 mi
Registration #14	2019-05-20	80.277 mi
Registration #15	2019-05-20	80.277 mi
Registration #16	2019-05-20	80.277 mi
Registration #17	2019-05-20	80.277 mi
Registration #18	2019-05-20	80.277 mi
Registration #19	2019-05-20	80.277 mi
Registration #20	2019-05-20	80.277 mi
Registration #21	2019-05-20	80.277 mi

More info >





Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1312 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC7063370